| | LICENSEE EVENT REPORT |
|------------|--|
| | CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) |
| 0 1 7 8 | N C B E P 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 5 EICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58 |
| CON'T | REPORT L 6 0 5 0 - 0 3 2 4 7 0 7 1 5 8 2 8 0 8 1 3 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 |
| 0 2 | During the on-going 1982 refueling outage, performance of Drywell to Torus Leak Rate |
| 0 3 | Test, PT 20.6, revealed that drywell to torus vacuum breakers X18 A, C, and E were |
| 0 4 | leaking excessively, resulting in a total leakage between the drywell and torus |
| 0 5 | greater than the equivalent leakage through a one inch diameter orifice at a d/p of |
| 0 6 | one psi. This event did not affect the health and safety of the public |
| 0 7 | Technical Specifications 3.6.4.1a, 6.9.1.9b |
| 0 8 7 8 | SYSTEM CAUSE CAUSE CUMP. VALVE |
| 0 9 7 8 | CODE SUBCODE S |
| | NUMBER 21 22 23 24 26 17 28 29 30 31 32 ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER S |
| 10 | Inspection of the valves' seating surfaces revealed debris had prevented an adequate |
| 11 | sealing surface. The valves were cleaned to remove the debris and the PT was |
| 1 2 | satisfactorily completed with zero leakage on July 15, 1982. An analysis of the debris |
| 13 | found is currently being performed and a supplement will be issued upon its completion. |
| 1 4 7 8 | PACILITY OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION (32) |
| 1 5 | H 28 0 0 0 0 29 NA B 31 Periodic Test |
| | ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA 44 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 AMOUNT OF ACTIVITY 35 NA 45 LOCATION OF RELEASE 36 |
| 7 8 | 9 PERSONNEL INJURIES 13 80 |
| 1 8 | 0 0 0 40 NA 9 11 12 8208200288 820813 80 LOSS OF OR DAMAGE TO FACILITY (43) PDR ADDCK 05000324 |
| 1 9 | TYPE DESCRIPTION NA S PDR |
| 2 0 | PUBLICITY ISSUED DESCRIPTION 45 NA NA NA NA NA NA NA NA NA N |
| 7 8 | M. J. Pastva. Jr. PHONE 919-457-9521 |