

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | A | L | B | R | F | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
8 9 14 15 25 26 30 37 40 47 54 57, CAT 58

ONT
1 | L | 0 | 5 | 0 | 0 | 0 | 2 | 6 | 0 | 7 | 1 | 0 | 2 | 1 | 8 | 1 | 8 | 0 | 3 | 0 | 4 | 8 | 2 | 9
2 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 | During normal oper. with unit 2 at full power SI 4.1.B. 2 (average power range
3 | monitor output signal calibration) was not performed within the required frequency.
4 | (Tech Spec Table 4.1.B) during the period 10/14/81 to 10/28/81. There
5 | was no effect on the health or safety of the public because APRM gains
6 | are monitored and recorded every 12 hours and log review indicates
7 | no APRM gains were out of tolerance. The test was satisfactorily per-
8 | formed on 10/14 and 10/28. See attachment for previous similar events.

0 | 0 | I | A | A | C | Z | Z | Z | Z | Z | Z | Z | Z | Z | Z | L | Z | 8 | 2 | - | 0 | 1 | 0 | / | 0 | 3 | L | - | 0 | H | H | Z | Z | 0 | 0 | 0 | 0 | Y | N | Z | Z | 9 | 9 | 9 | 9
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 | 0 | Personnel error. Personnel involved were instructed to be more careful
1 | 1 | when scheduling, performing, and routing surveillance instructions in
1 | 2 | the future. The existing surveillance program is fully adequate
1 | 3 | considering the few occurrences and the number of SI's performed
1 | 4 | (approximately 14,000/yr) and no further recurrence control is planned.

1 | 5 | E | 0 | 9 | 9 | NA | A | Plant Services Observation
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 | 6 | Z | Z | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 | 7 | 0 | 0 | 0 | Z | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 | 8 | 0 | 0 | 0 | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 | 9 | Z | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 | 0 | N | NA
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 82010 Technical Specification Involved Table 4.1.B

Reported Under Technical Specification 6.7.2.b.(3)* Date Due NRC 03/10/82

Event Narrative:

During normal operation with units 1 & 2 at approximately full power and unit 3 in refueling outage, SI 4.1.B.2 for unit 2 was not performed from 10/14/81 to 10/28/81. Technical Specification Table 4.1.B requires this SI to be performed once every seven days.

There was no effect on public health and safety. APRM gains are constantly monitored by the nuclear engineers and recorded once every 12 hours and Surveillance Instruction 4.1.B.2 for unit 2 was performed on 10/14/81 and 10/28/81. Maintenance personnel were instructed to be more careful when scheduling SI's in the future.

Regarding the actual missed performance of the SI, no further recurrence control is required as described in the LER. However, we are investigating the reason for the delay in recognizing that the SI was missed, and will take necessary actions to correct the situation.

* Previous Similar Events:

LER No. - 259/79023, 259/79029, 259/80009, 259/80057, 259/80068, 296/80017 and 260/81010

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: JRP