

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259/82054 Technical Specification Involved 3.7.A.2

Reported Under Technical Specification 6.7.2.a.(9) * Date Due NRC 8/20/82

Event Narrative:

Units 1 and 2 were in cold shutdown (0-percent power); unit 2 was in refueling outage (0-percent power). The unit 1 drywell and torus purge system had a branch line that connected to the process line and was anchored to the floor. This arrangement would not accommodate process line movement in a seismic event without failure. The problem was discovered during a branch line analysis of torus attached piping for IE Bulletin 79-14. The problem does not exist on units 2 or 3. A failure could have resulted in loss of primary containment with a seismic event. Corrective action was the removal of stanchion supports H16 and R36 and the connection with a U-bolt to an existing penetration support in accordance with design specifications. There was no effect on public health and safety. Primary containment remained intact.

* Previous Similar Events:

BFRO-50-259/79018, 79032, 80005, 80017, 81003

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: JRP