LICENSEE EVENT REPORT
CONTROL BLOCK: [ ] ] ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N C B E P 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT 58
CON'T  O 1 SOURCE L 6 0 5 0 - 0 3 2 5 7 0 7 2 2 8 2 8 0 8 2 0 8 2 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  Routine operator surveillance during plant shutdown operations revealed that SRM A
old indicated a count rate of 7 while SRMs C and D were indicating a count rate of 100-120.
[0 4] SRM B had been declared inoperable on 11-15-81, due to delayed indication response.
This event did not affect the health and safety of the public.
Technical Specifications 3.3.5.4b, 6.9.1.9b
0 7
08
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
COMPONENT   COMP
1 0 Intermittent failure of the power supply in SRM A caused the erroneous indication by
[1] that monitor. The power supply, Part No. NBO5, was replaced and indications exhibited
by SRM A returned to normal. The problem with SRM B will be fully investigated and
1 3 resolved during the upcoming refueling outage.
1 4 L 7 8 9 FACULTY (20) METHOD OF
STATUS % POWER OTHER STATUS DISCOVERY DISCOVERY DESCRIPTION (32)  1 5 G 28 0 0 0 0 29 NA A 31 Operator Surveillance
7 8 9 10 12 13 44 45 46 80  ACTIVITY CONTENT AMOUNT OF ACTIVITY (35)  NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA  NA  PERSONNEL INJURIES  NA  NA  80
PERSONNEL INJURIES NUMBER DESCRIPTION (41) NA NA NA NA
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA  NA
PUBLICITY PDR ADOCK 05000325 PDR S P
NAME OF PREPARES M. J. PASTVA, JR. PHONE 919-457-9521