

### LICENSEE EVENT REPORT

CONTROL BLOCK: 

1	2	3	4	5	6
---	---	---	---	---	---

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40
---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

  
A L B R F 2 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CONT  

7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40
---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

  
L 6 0 5 0 0 0 2 6 0 7 0 7 2 0 8 2 8 0 8 1 2 8 2 9  
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

0 2 | During normal operation, while performing SI 4.7.D.1.B-1(A), (H<sub>2</sub>O<sub>2</sub> sys. isol. vlv. operability) "B" hydrogen analyzer became inoperable (T.S. 3.7.H.2) due to the failure of the torus hydrogen sample valve 2-FSV-76-65. There was no effect on public health and safety. "A" hydrogen analyzer was available and operable. T.S. 3.7.H.2 permits operation for 30 days with one hydrogen analyzer inoperable. "B" hydrogen analyzer was inoperable for about 10 days, until the refueling outage began.

0 8 | \_\_\_\_\_

0 9 | SYSTEM CODE: S E 11; CAUSE CODE: E 12; CAUSE SUBCODE: A 13; COMPONENT CODE: V A L V O P 14; COMP SUBCODE: E 15; VALVE SUBCODE: Z 16

17 LER NO REPORT NUMBER: 8 2 21 22; SEQUENTIAL REPORT NO.: 0 2 1 24 25; OCCURRENCE CODE: 0 3 28 29; REPORT TYPE: L 30; REVISION NO.: 0 32

ACTION TAKEN: A 18; FUTURE ACTION: D 19; EFFECT ON PLANT: Z 20; SHUTDOWN METHOD: Z 21; HOURS: 0 0 0 0 37 40; ATTACHMENT SUBMITTED: Y 23; NPRD-4 FORM SUB.: Y 24; PRIME COMP. SUPPLIER: L 25; COMPONENT MANUFACTURER: V 0 3 0 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑲

1 0 | Valcor Engineering Corporation Solenoid Operator P/N V52630-529-1 failed. The solenoid assembly was replaced, but the solenoid valve failed again while performing SI 4.7.D.1.B.1-(A). The valve will be repaired during the refueling outage. These failures will be investigated further, with results expected by 1/1/83.

1 5 | FACILITY STATUS: E 28; % POWER: 0 7 9 29; OTHER STATUS: NA 30; METHOD OF DISCOVERY: B 31; DISCOVERY DESCRIPTION: Surveillance testing 32

1 6 | ACTIVITY CONTENT RELEASED: Z 33; AMOUNT OF ACTIVITY: NA 35; LOCATION OF RELEASE: NA 36

1 7 | PERSONNEL EXPOSURES: 0 0 0 37; DESCRIPTION: Z 38; NA 39

1 8 | PERSONNEL INJURIES: 0 0 0 41; DESCRIPTION: NA 42

1 9 | LOSS OF OR DAMAGE TO FACILITY: Z 43; DESCRIPTION: NA 44

2 0 | PUBLICITY ISSUED: N 45; DESCRIPTION: 8208270291 820812 PDR ADOCK 05000260 S PDR 46

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 82021 Technical Specification Involved 3.7.H.2

Reported Under Technical Specification 6.7.2.b.(2)\* Date Due NRC 8/19/82

Event Narrative:

Unit 1 was operating at 89-percent power and unit 3 was operating at 96-percent power. Both units were unaffected by this event. With unit 2 operating at 79-percent power, during the performance of Surveillance Instruction (SI) 4.7.D.1.B-1( A) (H<sub>2</sub>O<sub>2</sub> System Isolation Valve Operability), "B" hydrogen analyzer became inoperable due to the failure of torus hydrogen sample valve 2-FSV-76-65. There was no effect on public health and safety. A hydrogen analyzer was available and operable. Technical Specification 3.7.H.2 allows operation for 30 days with one hydrogen analyzer operable. The solenoid assembly was replaced. The solenoid assembly for 2-FSV-76-65 failed again during the performance of SI 4.7.D.1.B-1(A). Solenoid valve 2-FSV-76-65 will be repaired during the refueling outage which began July 30, 1982. These failures will be evaluated further with results expected by January 1, 1983.

\* Previous Similar Events:

LER BFRO-50-296/82019, 81037  
BFRO-50-259/82022

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision: JRP