

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 A R A N 0 2 0 0 - 0 0 0 0 - 0 0 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 58

CONT
0 1 REPORT SOURCE L 0 5 0 0 0 3 6 8 7 0 7 0 4 8 2 0 7 2 7 8 2 9

DOCKET NUMBER 60 61 EVENT DATE 68 69 REPORT DATE 74 75

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 On 7/4/81 while in Mode 1 at 100% full power, the containment high range

0 3 radiation monitor (2RITS-8925-2) failed. This caused entry into action A

0 4 of T.S. 3.3.3.6 which requires the monitor to be returned to operable

0 5 status within 30 days. The monitor was returned to operable status within

0 6 9 days. Portable equipment was available if needed. This occurrence is

0 7 reportable per T.S. 6.9.1.9.b. Containment radiation monitor 2RITS-8925-1

0 8 remained operable.

SYSTEM CODE B A 11 CAUSE CODE B 12 CAUSE SUBCODE C 13 COMPONENT CODE Z Z Z Z Z Z 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16

LER-NO REPORT NUMBER 17 EVENT YEAR 8 2 SEQUENTIAL REPORT NO 0 2 4 OCCURRENCE CODE 0 3 REPORT TYPE L REVISION NO 0

ACTION TAKEN B 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 ATTACHMENT SUBMITTED N 23 NRC-4 FORM SUB N 24 PRIME COMP SUPPLIER Z 25 COMPONENT MANUFACTURER Z 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 Troubleshooting revealed that two power supply leads had loosened on a ter-

1 1 minal block in the instrument cabinet associated with 2RITS-8925-2. The

1 2 loosened leads were tightened. All other leads were checked for tightness,

1 3 and no other loose connections were observed. The root cause apparently

1 4 was inadequate tightening of the connections during (continued on attachment)

FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 ROUTINE SURVEILLANCE 32

ACTIVITY CONTENT RELEASED OF RELEASE Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

PUBLICITY ISSUED N 44 DESCRIPTION NA 45

8208270305 820813
PDR ADOCK 05000368
S PDR

NAME OF PREPARER Patrick Rogers PHONE 501/964-3100

NRC USE ONLY

ATTACHMENT

LER NO. 50-368/82-024/03L-0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (Continued)

installation which occurred approximately six (6) months prior to this occurrence.