

No violations or deviations were identified in this area. The results of inspections in the surveillance area indicate that personnel conducted assigned activities in accordance with applicable procedures.

6. FNP's Error Reduction Program (STAR)

During this reporting period, the inspectors noted two incidents which, because of the self-verification ("STAR") program used by licensee personnel, prevented further problems:

- On September 25, an FNP security officer noticed that fire protection (FP) piping was iced over. Realizing that this condition was abnormal, control room (CR) personnel were immediately notified. Just prior to the call, CR personnel had received a FP alarm and indications of breaker trip. The actions of the security officer, along with the alarm and breaker indications, allowed for prompt identification of where CO2 had been discharged to the Unit 2 auxiliary building.
- One electrician and two systems operators (SO) were involved with a tagging order for the river water air system. One SO noted a small amount of oil at the base of the number 4 river water pump and personnel determined that the oil was leaking from the upper reservoir drain plug. In an attempt to tighten the plug, by hand, the drain plug broke off and an SO immediately plugged the hole using his hand. The other SO immediately called the CR, the pump was secured and the oil was drained from the pump. Repairs were made and a resumption of continued pump operation was possible the next day. Prompt action by the individuals involved prevented extensive damage to the motor and prevent oil from reaching the river.

7. Training for Emergency Preparedness (82206)

On October 20, the resident inspectors and Region II section chief observed portions of an FNP "full-scale" training exercise. The exercise was conducted as part of training for one of the designated emergency preparedness response groups. The Plant Assistant General Manager - Operations, served as the Emergency Director during the exercise and the Plant Assistant General Manager - Plant Support, served as the Recovery Manager. All designated plant personnel responded appropriately and expeditiously to the emergency alarms and the overall drill scenario.

8. Action on Previous Inspection Findings (92700)

- (Closed) Unit 1, URI 50-348/93-21-01, Oil mist in charging pump rooms.

The inspectors and FNP personnel inspected the "1A" and "1C" charging pumps and observed that internal motor conditions were acceptable. Oil present was insufficient to create problems and debris found would not