(7.77)	LICENSEE EVENT REPORT
. *	CONTROL BLOCK:
	V T V Y S 1 2 0 0 - 0 0 0 0 - 0 0
	REPORT L 6 0 5 0 0 0 2 7 1 0 0 5 3 1 8 2 8 0 6 3 0 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
02	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During normal operation, visual rod position indication was lost leaving only the com-
0 3	puter readout available. Power supply PSX6 was noticed to be extremely hot. Rod
0 4	position indication is required to be operable by Tech. Spec. 3.2.6. There were no
0 5	adverse conditions affecting the public health and safety. Similar occurrences
06	reported to the Commission were LER 80-4/3L and 82-8/3L.
07	
08	L
09	SYSTEM CAUSE CAUSE CAUSE COMPONENT CODE COMPONENT CODE SUBCODE
	SEQUENTIAL OCCURRENCE REPORT REVISION (17) REPORT 8 2 - 0 1 1 0 3 1 1 0
	ALTION FUTURE EFFECT SHUTDOWN TAKEN ACTION ON PLANT METHOD HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
110	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) This event was caused by the failure of the cooling fan in the power supply manufactured
	by Trygon Electronics Inc., model L5R6-70-OVST4626. The corrective action was to re-
112	place the power supply and verify satisfactory operation.
13	
	80
1 5	Beneficiality STATUS POWER OTHER STATUS Image: Status OTHER STATUS Image:
	ACTIVITY CONTENT RELEASE OF RELEASE AMOUNT OF ACTIVITY 35 I Z 33 Z 34 NA 44 45 LOCATION OF RELEASE 36 NA 80
17	PERSONNEL EXPOSURES NUMBER 0 0 0 0 37 Z 38 NA
19	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA
20	PUBLICITY ISSUED DESCRIPTION (45) 9207130202 820630 N (44) DESCRIPTION (45) S PDR ADOCK 05000271 PDR ADOCK 05000271
8	NAME OF PREPARER Warren P. Murphy PHONE: (802) 257-7711

-