

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 8 | _____ 8

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

8 9
FACILITY STATUS (28) 1 5 G
% POWER 0 0 0 (29) NA
OTHER STATUS (30)
METHOD OF DISCOVERY (31) C
DISCOVERY DESCRIPTION (32) Technical Review

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
1	7	000	Z	NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	40
		NA			

1		9		Z		42		DESCRIPTION		43	
								NA			

PUBLICITY
 ISSUED DESCRIPTION (4) 8208300110 820823
 2 0 N 44 PDR ADOCK 05000324
 S PDR NA

PHONE: 919-457-9521

LER ATTACHMENT 2-82-84

Facility: BSEP Unit No. 2

Event Date: August 10, 1982

As part of an ongoing review of testing procedures for technical adequacy, it was determined that Control Building ventilation dampers, 2J-D-CB (exhaust plenum suction for the emergency SGBTs) and 2L-D-CB (normal ventilation makeup), would remain "as is" on an isolation signal for high chlorine. These dampers should close to isolate the Control Room from the detected chlorine. The normal configuration for these dampers is one open and one shut, depending on the mode of ventilation (normal/emergency recirculation). No other problems were identified with the high chlorine logic.

Engineering is preparing a modification which will cause these dampers to close on a detected high chlorine signal. Our A/E, United Engineers & Constructors, was contacted on this deficiency and it appears that this was a design inadequacy during initial design.