## YANKEE ATOMIC ELECTRIC COMPANY



000

Rowe, Massachusetts 01367

March 13, 1981

Mr. B. H. Grier, Director U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region I 631 Park Avenue King of Prussia, Pennsylvania 19406

Subject: Licensee Event Report 50-29/81-03/03L

Containment Pressure Less Than 0.75 psig

In accordance with Technical Specifications, Section 6.9.4.b, the attached Licensee Event Report is hereby submitted.

Very truly yours,

Mealunt a. auto

Herbert A. Autio Plant Superintendent

LDF/meg

Enclosure:

- cc: [30] Director, Office of Inspection and Enforcement (USNRC)
  - [ 3] Director, Office of Management Information & Program Control (USNRC)
  - [14] NSARC Chairman (YAEC)

[1] Manager of Operational Quality Assurance (YAEC)

- [1] Institute of Nuclear Power Operations (INPO)
- [1] Nuclear Safety Analysis Center (NSAC)

RT: 17-R-04-013 IMS: D-Ø6-Ø1-Ø1

8209010250 810313 PDR ADDCK 05000029 5 PDR

7.7 LICENSEE EVENT REPORT (3/27) CONTROL BLOCK: 0316141400 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 0 0 3 0 0 0 0 -10 10 0 1 (2)CON'T 0 5 0 0 0 0 2 9 0 0 2 1 3 8 1 8 0 3 1 3 8 1 9 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 0 1 REPORT SOURCE DOCKET NUMBER EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [During normal operation in Mode 1, an auxiliary operator found containmen 0 2 It pressure to be 0.72 psig. T.S.3.6.1.7.a requires a minimum pressure of 0 3 0.75 psig. Personnel immediately verified that a loss of containment in 0 4 Itegrity had not occurred. A similar event was reported as LER 77-21. The 0 5 Ire were no adverse effects to the public health or safety as a result of 0 6 this event. 0 7 INSTRU SYSTEM CODE CAUSE CAUSE COMP VALVE SUBCODE CODE SUBCODE SUBCODE IA 16 OCCURRENCE CODE REVISION SEQUENTIAL REPORT NO. LER RO EVENT YEAR TYPE NO. 10 13 REPORT 0 0 3 0 NUMBER COMPONENT PRIME COMP. SUBMITTED NPRD-4 ACTION FUTURE TAKEN ACTION (22) HOURS SUPPLIER MANUFACTURER FORMSUB ×191919 N 24 Z 25 0 0 0 (21) 0 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The root cause of this event has been attributed to abnormally high amb 1 0 ent barometric pressure which caused the containment gauge pressure to ubstantially decrease. Containment absolute pressure remained essential y constant. An air charge was conducted to retain containment gauge presure to within T. S. Limits. No further actions are deemed necessary. 1 14 METHOD OF DISCOVERY OTHER STATUS (30) DISCOVERY DESCRIPTION (32) S POWER 0 9 8 29 E 28 N/A Operator Observation A ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (34) OF RELEASE RELEASED (33) (34) PERSONNEL EXPOSURES DESCRIPTION (39) UMBER TYPE NUMBER 33 N/A PERSONNEL INJURIES DESCRIPTION (41) UMAER 000 N/A LOSS OF OR DAMAGE TO FACILITY (43) 1(42 N/A PUBLICITY NRC USE ONLY N 44 DESCRIPTION 45 11/3 11111 NAME OF PREPARER \_\_\_\_\_ L. D. FRENCH (413)625-6140 PHONE -

19