LICENSEE EVENT REPORT (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) CONTROL BLOCK: 0 0 0 0 -T'NO 0 | 6 | 0 | 3 | REPORT 0 1 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10 During normal operation the "B" auxiliary feed pump started and ran due to a failed 0 2 diaphragm in the control valve. It was necessary to shut down the pump to repair 0 3 the diaphragm. This is operating in a degraded mode per Technical Specifications, 0 4 3.8 and reportable per Technical Specifications Section 6.9.2.b(2). Redundant 0 5 equipment was proved operable. There is no effect on the health and safety of the 0 6 public. 0 7 0 8 COMP VALVE CAUSE SYSTEM CAUSE COMPONENT CODE SUBCODE CODE CODE HI (15 LIVIEIX 1014 | H 0 9 REVISION OCCURRENCE REPORT SEQUENTIAL REPORT NO. CODE TYPE NO. EVENT YEAR LER/RO 0 10 13 IL 01016 REPORT NUMBER PRIME COMP COMPONENT NPRD-4 ATTACHMENT SUBMITTED SHUTDOWN (22) FORM SUB MANUFACTURER HOURS ON PLANT N 24 N 23 A 25 M | 1 | 2 ! 0 0101010 (18) Z 2 /(21 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The diaphragm failed at the point of maximum flexure stress in the air actuator. 1 0 This is Mason Nielan, air operated 2" plug type control valve model number 37-20521. 1 1 The same diaphragm on the redundant auxiliary feed pump will be replaced. 1 2 1 3 1 4 METHOD OF FACILITY (30) DISCOVERY DESCRIPTION (32) % POWER OTHER STATUS Operator Observation A (31 N/A 80 CONTENT ACTIVITY LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35 RELEASED OF RELEASE N/A N/A Z Z (34) (33) 1 6 80 PERSONNEL EXPOSURES DESCRIPTION (39) 137 Z 38 NUMBER N/A 01010 1 7 80 PERSONNEL INJURIES DESCRIPTION (41) NUMBER N/A 0 10 1 8 80 LOSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION N/A 2 /(42 1 9 10 8209020029 810625 PDR ADDCK 05000213 NRC USE ONLY PUBLICITY DESCRIPTION (45) N 144 PDR J. H. Ferguson (203)267-2556 PHONE:-NAME OF PREPARER