

LICENSEE EVENT REPORT

RB 6-9

7/16 4/11/8

CONTROL BLOCK: 0369421

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N Y J A F 1 2 0 0 - 0 0 0 0 - 0 0 0 0 3 4 1 1 1 1 4 D 5

CON'T 01 REPORT SOURCE L 5 0 5 0 0 0 3 3 3 7 0 4 1 0 8 1 3 0 5 0 8 8 1 3

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During normal operation, following conduct of surveillance required by Technical Specification 4.5.E.1.b., the RCIC turbine would not trip from the control room. 03 RCIC was removed from service when required by Technical Specification 3.5.E. to be operable to effect repair. The HPCI system was operable. No significant hazard existed.

09 SYSTEM CODE C E 11 CAUSE CODE X 12 CAUSE SUBCODE Z 13 COMPONENT CODE TURBINE 14 COMP SUBCODE Z 15 VALVE SUBCODE Z 16

17 LER NO REPORT NUMBER 81 22 EVENT YEAR 81 23 SHUTDOWN METHOD Z 21 24 SEQUENTIAL REPORT NO. 033 27 HOURS 0000 28 OCCURRENCE CODE 03 29 REPORT TYPE L 31 REVISION NO. 0 32 ACTION TAKEN X 18 33 FUTURE ACTION Z 19 34 EFFECT ON PLANT Z 20 35 PRIME COMP. SUPPLIER N 25 36 SHUTDOWN METHOD Z 21 37 HOURS 0000 40 ATTACHMENT SUBMITTED N 23 41 NPRO-4 FORM SUB. N 24 42 COMPONENT MANUFACTURER T147 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 Dirt or poor lubrication of the trip linkage is believed to be the cause. Following disassembly, cleaning, lubrication and reassembly of the trip device linkage, operation was satisfactory. RCIC was returned to service within 5 hours. No additional action is required.

15 FACILITY STATUS E 18 19 POWER 087 20 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 32 DISCOVERY DESCRIPTION Surveillance

16 ACTIVITY CONTENT 7 33 7 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

20 PUBLICITY ISSUED N 44 DESCRIPTION 8209020066 810508 PDR ADOCK 05000333 S PDR

NAME OF PREPARER W. Verne Childs

PHONE 315-742-3840

NRC USE ONLY

493