LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REC	QUIRED INFORMATION
0 1 N J S G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 CENSE CODE 14 15 LICENSE NUMBER 25 26 LICEN	1 1 1 4 57 CAT 58 5
CON'T O 1 SOURCE L O O O O O O O O O	8 1 8 8 2 9 REPORT DATE 80
At 1005 hours, August 1, 1982, during surveillance testing of	the Fire Suppression
System, the operator discovered that No. 1 Fire Pump would not	start from auto-
matic initiation. The fire pump was declared inoperable, and	Action Statement
3.7.10.la was entered at 1015 hours. No. 2 Fire Pump was test	ed and was capable
of meeting system requirements in the event of a fire.	
07	
7 8 9	80
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD	SUBCODE SUBCODE
SEQUENTIAL REPORT NO. SEQUENTIAL REPORT NO. SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE CODE TYPE 17 NUMBER 21 22 23 24 26 27 28 29 30	
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB.	SUPPLIER COMPONENT MANUFACTURER A 25 X 9 9 9 9 26
33 34 35 36 37 40 41 42	43 44 47
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)	
Investigation revealed the cause to be a failed fuse on No. 1	Battery Charger. The
1 0 Investigation revealed the cause to be a failed fuse on No. 1	the battery. The
Investigation revealed the cause to be a failed fuse on No. 1 [1] I fuse was replaced and the battery charger was used to recharge	Pump was declared
Investigation revealed the cause to be a failed fuse on No. 1 [1] [fuse was replaced and the battery charger was used to recharge [1] [surveillance test was satisfactorily performed and No. 1 Fire [1] [operable. Action Statement 3.7.10.la was terminated at 1900 h	Pump was declared nours, August 1, 1982.
Investigation revealed the cause to be a failed fuse on No. 1 If use was replaced and the battery charger was used to recharge 1	Pump was declared nours, August 1, 1982. RY DESCRIPTION (32) esting
Investigation revealed the cause to be a failed fuse on No. 1 If use was replaced and the battery charger was used to recharge 1	Pump was declared nours, August 1, 1982. BY DESCRIPTION (32) esting BO BO BO BO BO BO BO BO BO B
Investigation revealed the cause to be a failed fuse on No. 1 [1] [fuse was replaced and the battery charger was used to recharge surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillance test was satisfactorily performed and No. 1 Fire [1] [Surveillanc	Pump was declared nours, August 1, 1982. RYDESCRIPTION 32
Investigation revealed the cause to be a failed fuse on No. 1 [1] fuse was replaced and the battery charger was used to recharge [1] surveillance test was satisfactorily performed and No. 1 Fire [1] operable. Action Statement 3.7.10.la was terminated at 1900 Method of Discovery Status [1] [2] Surveillance test was satisfactorily performed and No. 1 Fire [1] [3] operable. Action Statement 3.7.10.la was terminated at 1900 Method of Discovery Status [1] [4] [5] [6] [7] [8] [9] [8] [9] [9] [9] [9] [9] [9] [9] [9] [9] [9	Pump was declared nours, August 1, 1982. 80 RY DESCRIPTION (32) esting 80 10 FRELEASE (36) (A
Investigation revealed the cause to be a failed fuse on No. 1 If use was replaced and the battery charger was used to recharge surveillance test was satisfactorily performed and No. 1 Fire Isurveillance test was satisfactorily performed and No. 1 Fire Operable. Action Statement 3.7.10.la was terminated at 1900 to the status of the st	Pump was declared nours, August 1, 1982. BY DESCRIPTION (32) SSTING BY OF RELEASE (36) A 80 BO BO BO BO BO BO BO BO BO B
Investigation revealed the cause to be a failed fuse on No. 1 If use was replaced and the battery charger was used to recharge surveillance test was satisfactorily performed and No. 1 Fire Isurveillance test was satisfactorily performed and No. 1 Fire Operable. Action Statement 3.7.10.la was terminated at 1900 performed and No. 1 Fire Image: Status operable of the status operation op	Pump was declared nours, August 1, 1982. BO RY DESCRIPTION 32 esting BO AND RELEASE 36
Investigation revealed the cause to be a failed fuse on No. 1 1 fuse was replaced and the battery charger was used to recharge 1	Pump was declared nours, August 1, 1982. BY DESCRIPTION (32) SSTING BY OF RELEASE (36) A 80 BO BO BO BO BO BO BO BO BO B
Investigation revealed the cause to be a failed fuse on No. 1 If use was replaced and the battery charger was used to recharge 1 1	Pump was declared nours, August 1, 1982. RY DESCRIPTION 32 esting 80 10F RELEASE 36 80 80