

### UNITED STATES NUCLEAR REGULATORY COMMISSION **REGION II** 101 MARIETTA ST., N.W., SUITE 3100 ATLANTA, GEORGIA 30303

Report No. 50-395/82-38

Licensee: South Carolina Electric and Gas Company Columbia, SC 29218

Facility Name: V. C. Summer

Docket No. 50-395

License No. CPPR-94

Inspection at V. C. Summer Nuclear Station

Inspector:

Approved by: in

rownlee, Section Chief, Division of Project and Resident Programs

Signed

SUMMARY

Inspection on June 1-30, 1982

Areas Inspected

This routine, unannounced inspection involved 152 inspector-hours onsite in the areas of TMI Action Plan Item Followup, Open Item Followup, Unresolved Item Followup, Preoperational Test Results Review, Surveillance Test Procedures Review, and Licensee Identified Item Review.

Results

Of the six areas inspected, no items of noncompliance or deviations were identified.

# DETAILS

### 1. Persons Contacted

### Licensee Employees

- \*W. A. Williams, General Manager Nuclear Operations
- \*O. W. Dixon, Vice President Nuclear Operations
- \*O. S. Bradham, Station Manager
- \*J. G. Connelly, Deputy Plant Manager
- \*B. G. Croley, Assistant Manager, Technical Support
- \*S. J. Smith, Assistant Manager, Maintenance
- \*L. F. Storz, Assistant Manager, Operations
- \*A. R. Koon, Technical Services Coordinator
- \*S. S. Howze, Nuclear Licensing
- \*D. A. Lavigne, Director, Surveillance Systems
- \*H. I. Donnelly, ISEG

Other licensee employees contacted included technicans, operators and office personnel.

\*Attended exit interview

2. Exit Interview

The inspection scope and findings were summarized on June 8, and July 2, 1982, with those persons indicated in paragraph 1 above. The inspector also attended the next interview of P. Taylor on June 9, 1982 and W. Peery on June 11, 1982 and R. Goode on June 30, 1982.

3. Licensee Action on Previous Inspection Findings

(Open)(82-13-01) MSIV Lockery Devices. The applicant provided the inspector with a copy of documentation which verified that the MSIV's were assembled under QC supervision the last time the valves were assembled. The documentation also indicates that the valves were assembled in accordance with the vendor technical manual which indicates the proper method of turning the locking tabs. The inspector therefore feels that adequate assurance exits that the inner locking tabs are installed properly. However, the applicant has agreed to inspect the tabs during the next disassembly of the valves. Therefore, this item will remain open until that time.

(Closed)(82-09-04) Discrepancies in Fire Detection Installation. This item dealt with discrepancies between the SER Supplement No. 3 and the licensee's understanding of the SER. NRR and the licensee have reviewed the issues and the results will appear in the SER Supplement No. 4.

# 4. Unresolved Items

Unresolved items were not identified during this inspection.

5. Open Item Review

(Closed) (81-29-07) STP 103.001 and STP 103.002. The inspector reviewed a revised STP 103.001. This STP combines the earlier revision of STP 103.002 and STP 103.001. Findings were acceptable.

(Closed) (81-29-12) STP 128.002. The inspector reviewed a revised STP 128.002. Some problems still existed in the procedure. Two valves were omitted and a nonexistent valve was listed. The applicant committed to correct the procedure prior to implementation.

(Closed) (81-29-09) STP 144.001. The inspector reviewed STP 144.001. Findings were acceptable.

(Closed) (80-29-04) SOP-118 amd SOP-212. The inspector reviewed a revised SOP-118 and SOP-212. Findings were acceptable.

(Closed) (82-22-02) Training Issues. This item dealt with problems identified in Administrative Procedure (AP)-1101, "General Employee Training" and AP-1106, "Required Reading". The inspector reviewed revisions to both of these procedures. Findings were acceptable.

(Closed) (81-28-07) SOP-401 and SOP 405. This item involves comments made on System Operating Procedures (SOP)-401 and 405. The inspector reviewed revisions made to these procedures. Findings were acceptable.

(Closed) (80-01-02) This item dealt with having as-built flow diagrams or appropriately controlled marked-up drawings available in the control room. The inspector reviewed the drawings in the control room. Findings were acceptable.

(Closed) (82-06-02) This item dealt with having as-built flow diagrams or appropriately controlled marked-up drawings available in the control room. The inspector reviewed the drawings in the control room. Findings were acceptable.

(Closed) (81-03-08) Human Factor Review. The item dealt with a number of items the applicant committed to implement concerning human factors changes in the control room. The inspector reviewed all the changes in conjunction with TMI Action Plan I.D.1. Findings were acceptable.

(Closed) (81-23-03) Plant Procedures Comments. This item dealt with a number of comments concerning the scope and administrative control of plant procedures. All items have been resolved.

(Closed) (81-32-06) This item dealt with some inconsistencies in the preoperational test program with regard to Regulatory Guide 1.79, 1.68 and

1.9. These inconsistencies have been resolved by providing documentation to verify that the requirements in the Regulatory Guides have been met.

#### 6. Surveillance Test procedure Review

The inspector reviewed the following Surveilllance Test Procedure (SPT):

Steam Generator Pressure/Temperature Verification 107.001 105.008 CHV/SI Pump Breaker Position Verification 105.001 CHV/SI Pump Test 105.009 Accumulator Interlock Refueling Test 104.001 Boric Acid Makeup to CVCS 104.004 Boric Acid Transfer Heat Tracing 126.002 Fuel Handling Building Operability Test 128.002 Fire Protection Monthly Valve Lineup Verification 128.401 Diesel Fire Pump Inspection 128.017 Weekly Inspection of Fire Doors 128.010 Fire Hose Station Refueling Inspection 128.007 CO<sub>2</sub> System Valve Lineup Verification Electric Fire Pump Monthly Test 128.001 128.003 Fire Protection Annual Valve Test 128.014 Cycling of Valves Not Testable during Operation 128.024 CO<sub>2</sub> System Functional Refueling Test 146.002 Reactor Makeup Water Refueling Alignment 149.015 Hydrostatic Test of RCP A, B, and C Seal Return Line 128.402 Fire Yard Hydrant Annual Inspection 134.001 Calculation of Shutdown Margin 147.001 Reactor Building Penetration Test 342.004 Condensate Storage Tank Level Instrument 3621 342.005 Condensate Storage Tank Level Instrument 3631 124.001 Control Room Emergency Air Cleanup system Operational Test 127.001 Pressurizer Valve Operability Test 125.006 Diesel Generator Refueling Operability Test 104.003 Boron System Monthly Valve Lineup Verification Test 111.001 Seismic Instrumentation Channel Check 125.001 Electrical Power System Weekly Test 125.002 Diesel Generator Operability Test 128.004 Diesel Fire Pump Weekly Test 403.002 Mechanical Snubber Visual Examination 501.001 DC Battery Quarterly Test 501.002 DC Battery Quarterly Test 501.003 DC Battery Service Test 501.004 DC Battery Capacity Test 501.005 DC Battery Charger Capacity Check 118.006 Reactor Building Purge Exhaust Refueling Weekly Test 131.001 Manipulator Crane Test 128.020 Fire Protection System Refueling Function Test 128.015 Fire Hose 3 year Inspection 127.003 PORV Overpressurization Protection Alignment Verification

128.013 Fire System Valve Operability Test

3

119.001 Hydrogen Recombiner Functional Test

123.001 Service Water Valve Linup

123.002 Service Water Pump Test

Findings were acceptable with the following exceptions:

- Some STP's written to implement the ASME Section XI Inservice Pump Program were not in accordance with ASME Section XI.
- (2) STP's written to implement the Fire Protection Surveillances in the Technical Specifications had numerous errors. Incorrect Technical Specifications errors, improper implementation of the surveillance requirements, requirements to verify valve positions of valves for which it is not possible to verify valve position and improper valve nomenclature are examples of some errors identified.
- (3) Some STP's did not adequately document the performance of the surveillance requirement.
- (4) One STP locked out the Motor Driven Emergency Feedwater Pumps during the verification of Diesel Generator Load Sequencer. The pumps should not have been locked out.

The applicant has been informed of all specific comments on the STPs. In no STPs reviewed could the inspector identify the placing of the plant in an unsafe condition. However there were numerous cases where an STP would not have properly implemented the Technical Specifications Surveillance Requirement or the STP would not have adequately documented the data required by Technical Specifications. The inspector informed the applicant that the errors identified in the STPs would be reviewed at a later date during plant startup.

7. Preoperational Test Results Review

The inspector reviewed the results of the following preoperational tests:

FH-2 Fuel Handling Buildings Storage Space Drag Test FH-3 Fuel Handling Machine and New Fuel Elevator FH-4 Fuel Transfer Test FH-5 Manipulator Crane Functional Test

The results were reviewed to ensure the indicated results were within the acceptance criteria and that the records indicated the test was performed in accordance with the procedure. Findings were acceptable.

8. 50.55(e) and Part 21 Review

(Open) (80-37-05) Inadvertent Boron Dilution. The applicant has notified Region II of a substantial safety hazard concerning inadvertent Boron dilution in correspondence dated November 20, 1982. In the letter dated February 10, 1982 the applicant indicated that plant tests were run to

measure the 'row rate of the reactor makeup water. The applicant indicated that the tests verified that the maximum flow condition was approximately 120 gpm and since the flow was well below the 150 gpm used in previous analyses, one reactor makeup water pump did not have to be unavailable. The inspector informed the applicant that not all the possible flow paths were verified during the test. The inspector requested a different flow path be tested. The test was run and the reactor makeup water flow was 150 gpm, the same as the assumed flow used in the analyses. The letter dated June 29, 1982 reports this condition to NRR.

Since the applicant had not submitted a final report on this subject the item will remain open. However, actions taken to date to preclude an inadvertent boron dilution are satisfactory to the NRC as indicated in the V. C. Summer SER. Therefore this item is no longer a fuel load restraint.

(Open) (82-38-01) Reactor Protection Underfrequency Relay Failure. In a letter dated June 14, 1982 the applicant reported that the reactor protection underfrequency relay's output contacts chattered. The underfrequency relays will be reviewed at a later date.

9. TMI Action Plan Item Followup

(Closed) II.B.2 Plant Shielding. This item requires:

- (1) A radiation and shielding design review that identifies the location of vital areas and equipment in which personnel occupancy may be unduly limited or safety equipment may be unduly degraded by radiation during operations following an accident resulting in a degraded core.
- (2) A description of the types of corrective actions needed to assure adequate access to vital areas and protection of safety equipment.

Supplement No. 1 to the V.C. Summer SER states that plant modifications were necessary in several areas. The inspector reviewed the modifications and inspected the implementation. Findings were acceptable.

(Open) II.F.2 Inadequate Core Cooling Instrumentation. Supplement No. 4 to the V. C.Summer SER indicated that the instrumentation installed is satisfactory for the first cycle of operation and that the schedule of June 1983 for installation of environmentally qualified incore thermocouples is acceptable to the staff. This item will remain open until then.

(Closed) I.B.1.2 Evaluation of Organization and Management Improvements of Near Term Operating License Applicants. This item was discussed in Inspection Report 50-395/82-06. The only issue remaining was to staff the Independent Safety Engineering Group (ISEG) with five dedicated fulltime site - based engineers. The inspector reviewed the staffing of the ISEG effective July 1982. Findings were acceptable.

(Closed) III.D.3.3. Inplant Radiation Monitoring. This item requires equipment, training and procedures necessary to accurately determine the

presence of airborne radioiodine in areas within the plant where plant personnel may be present during an accident. This item is discussed in the V. C. Summer SER. The inspector reviewed the equipment necessary to collect airborne samples and found that the equipment meets the requirements of NUREG 0737. The training and procedures were reviewed in Inspection Report 50-395/82-40.

(Closed) I.D.1 Control Room Design Review. This item requires a assessment of the control room to identify significant human factors deficiencies and instrumentation problems and to establish a schedule for correcting deficencies. An assessment of the V. C. Summer Control Room and Control Room Evacuation Panel was performed. Discepancies are identified in the V. C. Summer SER, through Supplement No. 4. The inspector has reviewed the changes made to correct all of the deficiencies. Findings were acceptable.

(Closed) II.B.3 Post Accident Sampling System. This item requires:

(1) a design and operational review of the reactor coolant and containment atmosphere sampling line system to determine the capability of personnel to promptly obtain a sample under accident conditions without incurring radiation exposure in excess of three and 18 3/4 rem to the whole body or extremities, respectively. Accident conditions should assume a Regulatory Guide 1.3 or 1.4 release of fission products. If the reveiw indicates that personnel could not promptly and safely obtain the samples, additional design features of shielding should be provided to meet the criteria.

This item is discussed in the V. C. Summer SER. The inspector reviewed the implementation of the commitments made in the SER and other correspondence referenced in the SER. Findings were acceptable.

(Closed) II.F.1 Accident Monitoring Instrumentation (Noble Gase Monitor, Iodine Particulate Sampling and Containment High Range Monitor)

This item deals with the requirement to have additional accident monitoring instrumentation. The Noble Gas Monitor, Iodine Particulate Sampling and Containment High Range monitor were reviewed in IE Inspection Report 50-395/82-40.