

ATTACHMENT 6  
LICENSEE EVENT REPORT

LAP 1500-5

Rev 2

Date March 12, 1982

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

FIL | L | SIC | \_\_\_\_\_ (2) | 0 | 10 | - | 10 | 10 | 10 | 10 | 10 | - | 10 | 10 | \_\_\_\_\_ (3) | 4 | 1 | 10 | 6 | 6 | \_\_\_\_\_ (4) | \_\_\_\_\_ (5)

LICENSEE CODE \_\_\_\_\_ LICENSE NUMBER \_\_\_\_\_ LICENSE TYPE \_\_\_\_\_

REPORT SOURCE \_\_\_\_\_ (6) | L \_\_\_\_\_ (7) | 0 | 15 | 10 | 10 | 10 | 13 | 17 | 13 | \_\_\_\_\_ (8) | 10 | 17 | 13 | 11 | 18 | 12 | \_\_\_\_\_ (9) | 0 | 18 | 13 | 11 | 18 | 19 | \_\_\_\_\_ (10)

DOCKET NUMBER \_\_\_\_\_ EVENT DATE \_\_\_\_\_ REPORT DATE \_\_\_\_\_

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

At 3:00 p.m. on July 31, 1982 during the performance of LIS-RH-12 differential pressure switch 1E31-N012A setpoint was found to exceed the allowable value per Technical Specification 3.3.2. A redundant pressure switch's setpoint was within the Tech. Spec. allowable value at the time of the surveillance.

SYSTEM CODE \_\_\_\_\_ (11) | C | F | \_\_\_\_\_ (12) | X | \_\_\_\_\_ (13) | X | \_\_\_\_\_ (14) | I | N | S | T | R | U | \_\_\_\_\_ (15) | S | \_\_\_\_\_ (16) | 7 | \_\_\_\_\_ (17)

CAUSE CODE \_\_\_\_\_ CAUSE SUBCODE \_\_\_\_\_ COMPONENT CODE \_\_\_\_\_ COMP. SUBCODE \_\_\_\_\_ VALVE SUBCODE \_\_\_\_\_

LEA/RO REPORT NUMBER \_\_\_\_\_ (18) | 8 | 2 | \_\_\_\_\_ (19) | 0 | 18 | 2 | \_\_\_\_\_ (20) | 0 | 3 | \_\_\_\_\_ (21) | L | \_\_\_\_\_ (22) | 0 | \_\_\_\_\_ (23)

ACTION TAKEN \_\_\_\_\_ (24) | E | \_\_\_\_\_ (25) | Z | \_\_\_\_\_ (26) | Z | \_\_\_\_\_ (27) | 0 | 0 | 0 | 0 | \_\_\_\_\_ (28) | Y | \_\_\_\_\_ (29) | N | \_\_\_\_\_ (30) | Z | \_\_\_\_\_ (31) | Z | 19 | 19 | \_\_\_\_\_ (32)

EFFECT ON PLANT \_\_\_\_\_ SHUTDOWN METHOD \_\_\_\_\_ HOURS \_\_\_\_\_ ATTACHMENT SUBMITTED \_\_\_\_\_ W/PRO. FORM SUB. \_\_\_\_\_ PRIME COMP. SUPPLIER \_\_\_\_\_ COMPONENT MANUFACTURER \_\_\_\_\_

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (37)

The cause of the instrument setpoint drift could not be determined. Trending is currently under way for Barton Models #288A - the 1E31-N012A type. Further corrective action will be performed if this trending shows continual setpoint drifting.

PLANT STATUS \_\_\_\_\_ (33) | B | \_\_\_\_\_ (34) | 0 | 0 | 0 | \_\_\_\_\_ (35) | NA | \_\_\_\_\_ (36) | B | \_\_\_\_\_ (37) | LIS-RH-12 | \_\_\_\_\_ (38)

METHOD OF DISCOVERY \_\_\_\_\_ DISCOVERY DESCRIPTION \_\_\_\_\_

ACTIVITY RELEASED OR RELEASE \_\_\_\_\_ (39) | Z | \_\_\_\_\_ (40) | Z | \_\_\_\_\_ (41) | NA | \_\_\_\_\_ (42) | NA | \_\_\_\_\_ (43)

PERSONNEL EXPOSURES NUMBER \_\_\_\_\_ (44) | 0 | 0 | 0 | \_\_\_\_\_ (45) | Z | \_\_\_\_\_ (46) | NA | \_\_\_\_\_ (47)

PERSONNEL INJURIES NUMBER \_\_\_\_\_ (48) | 0 | 0 | 0 | \_\_\_\_\_ (49) | \_\_\_\_\_ (50) | NA | \_\_\_\_\_ (51)

LOSS OF OR DAMAGE TO FACILITY TYPE \_\_\_\_\_ (52) | Z | \_\_\_\_\_ (53) | NA | \_\_\_\_\_ (54)

PUBLICITY DESCRIPTION \_\_\_\_\_ (55) | N | \_\_\_\_\_ (56) | NA | \_\_\_\_\_ (57)

8209030187 820831  
PDR ADOCK 05000373  
S PDR

NRC USE ONLY

R.W. Houston

I. LER NUMBER: 82-082/03L-0

II. LASALLE COUNTY STATION: UNIT 1

III. DOCKET NUMBER: 050-373

IV. EVENT DESCRIPTION:

At 3:00 p.m. on July 31, 1982 during the performance of LIS-RH-12 differential pressure switch 1E31-N012A setpoint was found to exceed the allowable value per Technical Specification 3.3.2.

V. PROBABLE CONSEQUENCES OF THE OCCURRENCE:

The reactor was in the cold shutdown mode at the time of the surveillance. A redundant pressure switch's setpoint was within the Technical Specification allowable value range. Safe plant operation was maintained at all times.

VI. CAUSE:

The cause of the instrument setpoint drift could not be determined.

VII. CORRECTIVE ACTION:

The 1E31-N012A pressure switch is a Barton Model #288A. Trending is currently under way for LIS-NB-01,02 and 03 for these Barton Models. Further corrective action will be performed if this trending shows continual setpoint drifting.

Prepared by: R.W. Houston