

ATTACHMENT G
LICENSEE EVENT REPORT

1-1-82-167

LAP 1500-5

Rev 2

Date March 12, 1983

CONTROL BLOCK: 1 1 1 1 1 1 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

23

LICENSEE CODE	14	15	LICENSE NUMBER	16	17	LICENSE TYPE	18	19	CAT. NO.	20
---------------	----	----	----------------	----	----	--------------	----	----	----------	----

REPORT SOURCE	11	12	13	14	15	DOCKET NUMBER	16	17	EVENT DATE	18	19	REPORT DATE	20
---------------	----	----	----	----	----	---------------	----	----	------------	----	----	-------------	----

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On August 2, 1982 during the performance of LIS-RI-04, RCIC Equipment Area High Temperature and High Vent Differential Temperature Isolation Calibration and Functional Test, temperature switch 1E31-N602A setpoint was found to exceed the allowable value per Technical Specification 3.3.1. A redundant RCIC Area High Temperature Isolation Switch was within the Technical Specification allowable value.

SYSTEM CODE	11	CAUSE CODE	12	CAUSE SUBCODE	13	COMPONENT CODE	14	COMP. SUBCODE	15	VALVE SUBCODE	16
CIE	9	E	11	E	12	IN IS IT IR IN	13	S	15	Z	16
17	18	19	20	21	22	23	24	25	26	27	28
LER/MO REPORT NUMBER	812	EVENT YEAR				SEQUENTIAL REPORT NO.	10 18 11	1	3	10 13	3
ACTION TAKEN	X	FUTURE ACTION	Z	EFFECT ON PLANT	Z	SHUTDOWN METHOD	10 10 10 10	Y	10	N	Z
21	22	23	24	25	26	27	28	29	30	31	32
HOURS	10	ATTACHMENT SUBMITTED	10	INTERNAL FORM S/N.	10	PRIME COMP. SUPPLIER	10	COMPONENT MANUFACTURER	10	10	10

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The cause of the setpoint deviation was attributed to setpoint drift of instrument 1E31-N602A. The instrument was recalibrated per the LIS-RI-04 procedure.

FAULTY STATUS	10	4 POWER	11	OTHER STATUS	12	METHOD OF DISCOVERY	13	DISCOVERY DESCRIPTION	14
B	10	10	10	NA	11	B	12	LIS-RI-04	13
ACTIVITY CONTENT	15	RELEASED OR RELEASE	16	AMOUNT OF ACTIVITY	17	45	46	LOCATION OF RELEASE	18
B	10	Z	11	NA	12	45	46	NA	19
PERSONNEL EXPOSURES	19	NUMBER	20	TYPE	21	DESCRIPTION	22		23
10	10	10	11	Z	12	NA	13		24
PERSONNEL INJURIES	25	NUMBER	26	TYPE	27	DESCRIPTION	28		29
10	10	10	11	Z	12	NA	13		30
LOSS OF OR DAMAGE TO FACILITY	31	TYPE	32	DESCRIPTION	33				34
Z	10	NA	11	NA	12	8209030257 820830	13	PDR ADDCK 05000373	14
PUBLICITY	35	DESCRIPTION	36			S	15	PDR	16
45	NA						16		17
46	NA						17		18
							18		19
							19		20
							20		21
							21		22
							22		23
							23		24
							24		25
							25		26
							26		27
							27		28
							28		29
							29		30
							30		31
							31		32
							32		33
							33		34
							34		35
							35		36
							36		37
							37		38
							38		39
							39		40
							40		41
							41		42
							42		43
							43		44
							44		45
							45		46
							46		47
							47		48
							48		49
							49		50
							50		51
							51		52
							52		53
							53		54
							54		55
							55		56
							56		57
							57		58
							58		59
							59		60
							60		61
							61		62
							62		63
							63		64
							64		65
							65		66
							66		67
							67		68
							68		69
							69		70
							70		71
							71		72
							72		73
							73		74
							74		75
							75		76
							76		77
							77		78
							78		79
							79		80
							80		81
							81		82
							82		83
							83		84
							84		85
							85		86
							86		87
							87		88
							88		89
							89		90
							90		91
							91		92
							92		93
							93		94
							94		95
							95		96
							96		97
							97		98
							98		99
							99		100

I. LER NUMBER: 82-081/03L-0

II. LASALLE COUNTY STATION: UNIT 1

III. DOCKET NUMBER: 050-373

VI. EVENT DESCRIPTION:

On August 2, 1982 during the performance of LIS-RI-04, RCIC Equipment Area High Temperature and High Vent Differential Temperature Isolation Calibration and Functional Test, temperature switch 1E31-N602A setpoint was found to exceed the allowable value per Technical Specification 3.3.1.

V. PROBABLE CONSEQUENCES OF THE EVENT:

The reactor was in cold shutdown at the time of the Instrument Surveillance. A redundant RCIC Area High Temperature Isolation Switch was within the Technical Specification allowable value. Safe plant operation was maintained at all times.

IV. CAUSE:

The cause of the setpoint deviation was attributed to setpoint drift of instrument 1E31-N602A.

VII. CORRECTIVE ACTION:

The instrument, 1E31-N602A, was recalibrated per the LIS-RI-04 procedure.

Prepared by: R. Houston