LICENSEE EVENT REPORT

CONTROL BLOCK:
01 COFSV1000-000-000-000-000-000-000-000-000-00
CON'T REPORT LIG 0 5 0 0 0 0 2 6 7 7 0 7 2 7 8 2 8 0 8 2 6 8 2 9
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 On July 27, 1982, with the reactor operating at approximately 70% power, Loop 2 emer-
old gency feedwater header to the helium circulator pelton wheel drives was isolated from
service for repair of pressure control valve, PV-21244. This is a degraded mode of
Fort St. Vrain Technical Specification LCO 4.2.2(a) and is reportable per
O 6 AC 7.5.2(b)2. Similar RO'S: 82-028, 82-015, 81-060, 81-054. No effect on public
0 7 health or safety.
7 8 9 SYSTEM CAUSE CAUSE COMP. VALVE
CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
17 REPORT 8 2
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMPONENT MANUFACTURER SUBMITTED FORM SUB TUPFLIER MANUFACTURER MANUFACT
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) 1 O Normal wear caused internal leakage through PV-21244, a Masoneillan, Model-71-20721,]
[1] L carbon steel. 2500# rated air operated diaphragm valve. Internals of valve were re-
[1] placed, and valve controller, PIC-21244, was recalibrated. Header was returned to
service. No further corrective action is anticipated or required.
1 4 1 8 9
FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 0 7 0 29 N/A A 31 Operator Observation 30
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35
1 6 Z 33 Z 34 N/A
17 LOI O 0 37 Z 38 N/A
PERSONNEL INJURIES NUMBER DESCRIPTION 41
1 8 0 0 0 0 (40) N/A 1 8 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION I 9 Z 42 N/A
PUBLICITY 45 PDR ADDCK 05000267 S PDR ADDCK 05000267 S PDR
(303) 785-2224
NAME OF PREPARER THE THE PHONE: