	Page 1 of 1
C	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 1	M S G G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT 58
ON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 4 1 6 7 0 8 0 4 8 2 8 0 9 0 2 8 2 9
-	VENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	On 8/4 at 0500 hours, the zone 2-15 smoke detector in the auxiliary building
0 3	185 ft. cable chase alarmed on the security/fire protection computer and
0 4	would not clear. There was no fire or smoke in the area. The system was
0 5	not returned to operable status within 14 days as required by T.S. 3.3.7.9.
06	
07	
7 8 9	
0 9 7 8	SYSTEM CAUSE CAUSE SUBCODE SUB
(TO LER/RO EVENT YEAR REPORT NO. REPORT NUMBER 21 22 23 24 26 23 20 20 20 20 20 20 20 20 20 20 20 20 20
AC'	TION FUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMPONENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
33	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
C	AUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	The condition was caused by malfunctioning hardware associated with the
TIL	security/fire protection computer multiplexer. The supervisory line
12 L	board was replaced to return the system to operable status on 8/27. An
13	hourly fire watch was established in accordance with T.S.3.3.7.9. The
1 4 L	multiplexer is part of the Data General System as supplied by Sygnetron.
FAC	H 28 0 0 0 29 NA METHOD OF DISCOVERY DESCRIPTION 32 Audio and Visual Alarm
	IVITY CONTENT 12 13 44 45 46 80 AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
1 6 2 7 8 9	Z 33 Z 34 NA
170	NUMBER TYPE DESCRIPTION (39) NA NA
7 8 9	PERSONNEL INJURIES NUMBER DESCRIPTION (41)
180	
	NA 8209080514 820902 80 S ADDCK 05000416 PDR NA PDR
	Z (42) NA
7 8 9	10 PHRIICITY 0
1881	10
ISSI	PUBLICITY UED DESCRIPTION 45 NRC USE ONLY

PHONE:___