	rage 1 of 1
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8	M S G S S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 B LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
0 1 7 8	REPORT L 6 0 5 0 0 0 4 1 6 7 0 8 0 4 8 2 8 0 9 0 2 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
[6] 6]	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 A plant service water isolation valve from Auxiliary Building to discharge
0 2	
0 3	basin, Q1P44-F118, was manually closed to comply with T.S.3.6.6.2 because
0 4	Q1P44-F119 failed to properly indicate its status as reported in LER 82-035/03L-0.
0 5	When F118 was closed it failed to properly indicate its status and is being
0 6	reported persuant to T.S.6.9.1.13.b.
0 7	
0 8	9 SYSTEM CAUSE CAUSE COMP. VALVE
0 9	W A (1) B (12) C (13) V A L V O P (14) SUBCODE
	SEQUENTIAL REPORT NO. SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE NO. OCCURRENCE REPORT TYPE NO.
	NUMBER 21 22 23 24 26 27 28 29 30 31 32 ACTION FUTURE EFFECT SHUTDOWN COMPONENT
	TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER [E] 18 [Z] 19 [Z] 20 [Z] 21 [O] O O O N 23 [N] 24 [A] 25 [B] 2 3 7 26
	33 34 35 36 37 40 41 42 43 44 47 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0	Snap-lock limit switches were not positioned correctly and gave dual
111	indications on control panel. Maintenance correctly positioned the limit
1 2	switches and retested the valve/indication successfully.
1 3	
1 4	
7 8	9 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
1 5	B 28 0 0 0 0 29 NA A A 31 Operator Observation 80
	ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
7 8	Z 33 Z 34 NA
1 7	NUMBER TYPE DESCRIPTION (39) NA NA
7 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8	NA NA
	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA
7 8	9 BIBLIOTY
20	ISSUED DESCRIPTION (45) NA PDR ADOCK 05000416 PDR 11111111
1 0	
7 8	