LICENSEE EVENT REPORT

	CONTROL BLOCK:
01	N J S G S 2 3 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 0 1 5
CON'T	PREPORT 1 101 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1
7 8	SOURCE 1 6 0 5 0 0 0 3 1 1 7 0 8 1 9 8 2 8 6 8 2 5 8 2 9
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 At 2145 hours, August 19, 1982, while checking accumulator sightglass level indication,
0 3	the Equipment Operator discovered a service water leak within the containment. An
04	investigation revealed that the leakage was from No. 25 Containment Fan Coil Unit
0 5	(CFCU). The CFCU was declared inoperable, isolated, and Action Statement 3.6.2.3.a
0 6	was entered. At 2240 hours, the NRC was notified by telephone with written confirm-
0 7	ation on August 20, 1982. Both containment spray systems were operable throughout
018	the occurrence.
	SYSTEM CAUSE CAUSE COMPONENT CODE COMP. VALVE SUBCODE SUBCODE SUBCODE SUBCODE SUBCODE
7 8	9 10 11 12 13 13 18 19 15 20 (16)
	17 REPORT NUMBER B 2 C T B C C C C C C C C C
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
	33 (18) A (19) [2] (20) [2] (21) [37] (19) [40] [41] (23) [N] (24) [A] (25) [W] 1 2 0 (26)
10	The cause was erosion of the copper nickel piping. The cooler was replaced and No. 25
11	CFCU was satisfactorily tested. Action Statement 3.6.2.3.a was terminated at 1630
1 2	hours, August 23, 1982. Design Change Request 2EC-0507 has been issued to replace the
1 3	cooler with a more erosion resistant material.
14	L
	POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
	9 10 12 13 NA 44 45 46 80
1 6	Z 33 Z 34 NA LOCATION OF RELEASE 36
	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
7 8	9 PERSONNEL INJURIES 13 80
1 8	NUMBER DESCRIPTION (41) O O O O NA
	LOSS OF OR DAMAGE TO FACILITY 43 B209080613 B20825 PDR ADDCK 0500031
, 8	9 10 PURILICITY 6
20	NAC USE ONLY R. Heller
	NAME OF PREPARER PHONE: (609) 541-5900 629
	THOUSE THE PARTY OF THE PARTY O