


1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	S	G	G	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5					
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58			59

CON'T

REPORT SOURCE L 0 5 0 0 0 4 1 6 7 0 8 1 0 8 2 8 10 9 0 8 8 2 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | While under a Limiting Condition for Operation imposed by a violation of

03 | T.S.3.7.7, daily fire door checks were not conducted on the days of June 17, 1982

04 | and June 24, 1982 as required by T.S.4.7.7.2. This is reportable under

05 | T.S.6.9.1.13.b.

06 | Page

07 | Page

SYSTEM CODE A B		CAUSE CODE A	CAUSE SUBCODE A	COMPONENT CODE X X X X X X X				COMP. SUBCODE Z	VALVE SUBCODE Z
11		12	13	18				19	20
EVENT YEAR 8 2		SEQUENTIAL REPORT NO. 0 4 6		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0	
21		24		28		30		32	
ACTION TAKEN G	FUTURE ACTION Z	EFFECT ON PLANT Z	SHUTDOWN METHOD Z	HOURS 0 0 0 0	ATTACHMENT SUBMITTED Y	NPRD-4 FORM SUB. N	PRIME COMP. SUPPLIER A	COMPONENT MANUFACTURER Z 9 9 9	
33	34	35	36	37	41	42	43	44	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Incomplete communication between operating shifts on these days was the probable

1 1 | cause. The immediate action was to increase personnel awareness of the performance

1	2
---	---

 and documentation requirements of the surveillance. Long term action has been to

1	3
---	---

 | revise operating practices and surveillance procedures.

1	4	
---	---	--

FACILITY STATUS (1) 5 (X) (28) % POWER (0) (0) (0) (29) OTHER STATUS (30) Pre-Core-Load METHOD OF DISCOVERY (B) (31) DISCOVERY DESCRIPTION (32) Surveillance Review

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 Z 33 Z 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0 0 0	(37) Z	(38) NA (39)					

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
0	0	0	40
		NA	

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52																																																									

7 8 9 10
PUBLCITY
ISSUED DESCRIPTION NA S PDR
2 0 Z 4 45
S

8209160180 820908
PDR ADOCK 05000416
NRC USE ONLY

NAME OF PREPARER Original Signed by G. S. Sparks

PHONE: _____

• 7.926

SUPPLEMENT TO
LER NO. 82-046/03 L-0

Licensee: Mississippi Power & Light Company
Facility: Grand Gulf Nuclear Station
Docket No: 05-000416

Daily fire door checks required by Specification 4.7.7.2 were not conducted on (two days) 6-16-82 and 6-24-82. This is reportable under Specification 6.9.1.13.b.

The checks were conducted on subsequent days up to and including the date of discovery. The probable cause was either inadequate turnover information about the status of the fire door checks between the operating shifts, or loss of the data sheets during routing and screening (prior to storage in the recovery vault).

Operating practices did not ensure adequate completion and retention of the surveillance data sheets.

Surveillance procedures have been modified to ensure that personnel of a specified shift are designated to complete the surveillance and that the status of the surveillance is documented from one shift to another shift. The routing of completed data sheets has been modified to reduce the number of people who review and screen them.