NAL FURM JUN (7.77) LICENSEE EVENT REPORT CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 10L - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 LICENSE NUMBER 25 26 LICENSE TYP G IS 0 0 5 CON'T REPORT 0 1 10 8 2 9 8 2 69 EVENT DATE B 0 9 0 3 8 2 9 74 75 REPORT DATE 80 0 0 SOURCE DOCKET NUMBER EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) At 2230 hours, August 29, 1982, an operator discovered a service water leak of .5 GPM 0 2 on No. 23 Containment Fan Coil Unit (CFCU). No. 23 CFCU was isolated and declared 0 3 inoperable. Because No. 24 CFCU was already inoperable, Action Statement 3.6.2.3b 0 4 was entered at 2235 hours. The NRC was notified by telephone in compliance with NRC 0 5 Bulletin 80-24, with written notice transmitted on August 30, 1982. 0 6 0 7 0 8 SYSTEM CAUSE CAUSE COMP SUBCODE CODE COMPONENT CODE SUBCODE B (13) 0 9 B B (16) SEQUENTIAL OCCURRENCE REVISION REPOR LER RO REPORT NO. CODE TYPE NO REPORT 8 0 8 4 01 T 0 NUMBER ATTACHMENT SUBMITTED EFFECT ON PLANT METHOD NPRD-4 PRIME COMP. COMPONENT HOURS (22) FORMSUB MANUFACTURER 0 0 (23 (25 (26) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The leakage was due to erosion of the copper nickel cooling coils. 10 The coil was 1 1 repaired with Belzona. The CFCU was declared operable and Action Statement 3.6.2.3b was terminated at 0700 hours, August 30, 1982. Design Change Request 2EC-0505 has 1 2 been issued to replace the coils with an erosion resistant material. 1 3 1 4 METHOD OF FACILITY OTHER STATUS (30) S POWER DISCOVERY DESCRIPTION (32) 1 5 (28 NA Containment Surveillance 80 ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) OF RELEASE Z 33 Z 34 1 6 NA NA 11 80 PERSONNEL EXPOSURES DESCRIPTION (39) 1 7 Z (38) 0 37 0 PERSONNEL INJURIES 80 DESCRIPTION (41) NUMBER 1 8 (40) NA LOSS OF OR DAMAGE TO FACILITY (3) 12 DESCRIPTION 1 9 Z (42) NA 10 09160191 820903 R ADDCK 05000311 PDR PUBLICITY NRC USE ONLY DESCRIPTION 45 PDR SUED (44 2 0 N 11111 68 69 R. Heller (609) 541-5900 629 NAME OF PREPARER. PHONE .