

Certified By

PH. BOYER
NORTON, CONNECTICUT
(203) 466-6911

October 1, 1982
MP-4188

NORTHWEST UTILITIES
THE AMERICAN LIGHT AND POWER COMPANY
THE NEW ENGLAND ELECTRIC COMPANY
THE NEW YORK STATE ELECTRIC COMPANY
CENTURY ENERGY SERVICES COMPANY
DIVISION OF FIRST ENERGY SERVICE

Mr. Ronald C. Haynes
Regional Administrator, Region 1
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
637 Park Avenue
King of Prussia, Pennsylvania 19406

Reference: Docket Number 50-245
Provisional License DPE-21
Reportable Occurrence 82-20/IP

Dear Mr. Haynes:

This letter is forwarded to provide prompt notification of Reportable Occurrence 82-20/IP as required by the Millstone Unit 1 Technical Specifications.

On September 30, 1982, at 1630 hours, while performing a Hydraulic Snubber Functional Test, one ITT Grinnell Snubber failed lock up and bleed rate requirements and three ITT Grinnell Snubbers failed the bleed rate requirements. Technical Specification 3.6.I.5 states that if a snubber is determined to be inoperable while the reactor is in shutdown or refueling mode, the snubber shall be made operable or replaced prior to reactor startup. An additional 10 percent of the same type of snubbers will be functionally tested.

Additional information, including immediate and long-term corrective actions, will be provided in a 14-day followup report.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

E. J. Mroczka
E. J. Mroczka
Station Superintendent
Millstone Nuclear Power Station

EJM/VST:mg

cc: Director, Office of Management Information and Program Controls
Washington, D. C. (2)
U.S. Nuclear Regulatory Commission, c/o Document Management Branch
Washington, D. C. 20555