



## SUPPLEMENTARY INFORMATION

REPORT NO: 50-302/82-057/03L-0

FACILITY: Crystal River Unit #3

REPORT DATE: October 1, 1982

OCCURRENCE DATE: May 27, 1982

### IDENTIFICATION OF OCCURRENCE:

Failure to perform required post maintenance stroke time testing on a containment isolation valve, contrary to the requirements of Technical Specification 4.6.3.1.1.

### CONDITIONS PRIOR TO OCCURRENCE:

Mode I, Power Operation, (71%).

### DESCRIPTION OF OCCURRENCE:

At 0900 on September 3, 1982, while reviewing surveillance records, it was discovered that service water valve (SWV-49) had not been stroke time tested after maintenance was performed. The valve was declared inoperable because stroke time testing of Containment Isolation Valves following maintenance is required to demonstrate valve operability. The valve was stroke time tested by and declared operable by 0950.

### DESIGNATION OF APPARENT CAUSE:

The cause of this event was personnel error.

### ANALYSIS OF OCCURRENCE:

Service water valve (SWV-49) was functionally tested after maintenance but not stroke timed as required. There was no effect upon the health or safety of the general public.

### CORRECTIVE ACTION:

The valve was immediately stroke time tested and maintenance planners instructed on technical specification requirements following maintenance of containment isolation valves. No further corrective action is necessary.

### FAILURE DATA:

This was the forty-fourth report under this specification, and the second failure to stroke time test a Containment Isolation valve following maintenance.