LICENSEF EVEN I REPORT
CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M N P I N 1 2 0 0 - 0 0 0 0 0 3 4 1 1 1 1 1 4 5 CAT 58 5
REPORT L G G 5 0 0 0 0 2 8 2 7 0 9 0 6 8 2 8 1 0 0 6 8 2 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 Following a reactor trip, a spike occurred in RCS activity up to 1.38 µCi/gm
Dose Equivalent I-131. See Attachment.
0[4] [
0 5 1
0 6 1
071
7 8 9 SYSTEM CAUSE CAUSE CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE
Taken action Future Effect Shutdown Method Me
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
Reactor trip and subsequent washout of fission products on the subsequent
power escalation. See Attachment.
112
7 8 9 8CULTY (30) METHOD OF (32)
TI 5 C 28 D 3 0 29 NA DISCOVERY DISC
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA NA NA NA NA 80
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 1 7 8 9 11 12 13 80
PERSONNEL INJURIES NUMBER DESCRIPTION 1 8 0 0 0 0 0 NA 8210130533 821006 PDR ADOCK 05000282 PDR 1 9 Z 42 NA 8210130533 821006 PDR ADOCK 05000282 PDR
7 8 9 10 PUBLICITY NRC USE ONLY ISSUED DESCRIPTION
2 0 N (44) NA
NAME OF PREPARER A. A. Hunstad PHONE: 612-388-1121

October 6, 1982 Attachment (Page 1 of 5)

NORTHERN STATES POWER COMPANY PRAIRIE ISLAND NUCLEAR GENERATING PLANT Docket No. 50-282

LER 82-016/03L-0

Event Description

The Unit 1 equilibrium primary coolant specific activity prior to September 6, 1982 was approximately 3 to 5 x 10 $^{-3}$ $\mu\text{Ci/gm}$ DOSE EQUIVALENT I-131. At 11:39 on September 5 the Unit 1 reactor tripped on low Steam Generator level as a result of loss of air to 12 Feedwater Reg. Valve. Sampling of the primary coolant specific activity following the trip and recovery indicated that a spike occurred in the DOSE EQUIVALENT I-131 activity up to a maximum of 1.38 $\mu\text{Ci/gm}$ which was greater than the 1.0 $\mu\text{Ci/gm}$ limit given in T.S.3.1.D.1.a.

In accordance with Tech. Spec. 3.1.D.4(a) the following information is provided.

a. Results of the specific activity analysis:

Date	Time	DOSE EQUIVALENT IODINE-131(µCi/gm)
9-3-82	0755	3.71×10^{-3}
9-4-82	0430	7.90×10^{-3}
9-5-82	0730	7.02×10^{-3}
	1153	1.35×10^{-2}
	1447	0.229
	1520	0.294
	1707	0.322
	1846	0.397
	2102	0.649
	2200	0.731
	2315	0.817
9-6-82	0015	0.917
	0318	1.38

LER 82-016/03L-0 October 6, 1982 Page 2 of 5

	0513	1.33
	0715	1.08
	0726	1.04
	0815	0.885
	1015	0.721
	1350	0.503
	1804	0.221
	2202	0.127
9-7-82	0203	4.52×10^{-2}
	0556	6.48 x 10 ⁻²
	0750	6.06×10^{-2}
9-8-82	0730	2.13×10^{-2}
9-9-82	0530	1.07×10^{-2}
9-10-82	0827	7.99×10^{-3}
9-11-82	0313	7.65×10^{-3}
9-12-82	0755	6.46×10^{-3}

b. Reactor power history starting 48 hours prior to the first sample in which the limit was exceeded:

See Figure 1

c. Fuel burnup by core region:

Fuel Region Number	Number of Assemblies	Burnup(MWD/MTU)*
6	1	37260
7	40	34943
8	40	23135
9	40	10441

*(At 11:39 on September 5, 1982)

d. Cleanup flow history starting 48 hours prior to the first sample in which limit was exceeded:

See Figure 2

LER 82-016/03L-0 October 6, 1982 Page 3 of 5

e. History of de-gassing operations, if any, starting 48 hours prior to the first sample in which the limit was exceeded:

No de-gassing operations were performed during this time period.

f. The time duration when the specific activity of the primary coolant exceeded 1.0 μ Ci/gm DOSE EQUIVALENT I-131:

Less than 8 hours.

This event had no effect on the health and safety of the general public. Equilibrium specific activity has returned to pre-trip levels.

Cause Description and Corrective Action

Unit 1 has been operating since early in Cycle 7 with known fuel defects (estimated 5 to 20 leaking rods). These defects are believed to be located in newest region of fuel (Region ... The spike in primary coolant specific activity occurred as a result of the reactor trip and subsequent "washout" of fission products from the existing defects on the subsequent power escalation. There is no evidence of new defects being formed as a result of this transient.


Cleanup flow was increased to 80 gpm until the activity had decreased below the limit.

Current planning is to remove the suspected region 9 fuel from the core during the cycle 7-8 refueling outage starting in November for repair.

PRAIRIE ISLAND UNIT #1 POWER HISTORY


LER 82-016/03L-0

October 6, 1982 Page 4 of 5



SEPT. 1 TO 13, 1982

PI I CYC 7 DEI 9/I TO 9/I3



LER 82-016/03L-0 October 6, 1982 Page 5 of 5

PURIFICATION GPM