

NOTICE OF VIOLATION

Budinger and Associates  
E. 3820 Broadway  
Spokane, Washington 99202

Report No. 90-01  
Docket No. 030-20415  
License No. 46-23250-01

During an NRC inspection conducted on September 10, 1990, violations of NRC requirements were identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1990), the violations are listed below:

- A. Condition 14 of the license states in part that a physical inventory shall be conducted every six months to account for all sources and/or devices received and possessed under the license.

Contrary to the above, at the time of the inspection, no physical inventories of licensed material had been conducted. This is a repetitive violation.

This is a Severity Level IV Violation (Supplement VI).

- B. Condition 13.C. of the license states in part that records of leak test results shall be maintained for inspection by the Commission and shall be kept in units of microcuries.

Contrary to the above, at the time of the inspection, leak test records were not maintained for leak tests conducted between July 6, 1988 and July 25, 1990. This is a repetitive violation.

This is a Severity Level V Violation (Supplement VI).

- C. 10 CFR Part 19.11 requires in part that each licensee post a current copy of 10 CFR Parts 19 and 20 and Form NRC-3, "Notice to Employees". If posting the documents is not practicable, the licensee may post a notice which describes the documents and states where they may be examined.

Contrary to the above, at the time of the inspection, no copy of 10 CFR Parts 19 and 20 or Form NRC-3, "Notice to Employees" were posted and no notice describing the documents and where they may be examined was posted. This is a repetitive violation.


This is a Severity Level V Violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, Budinger and Associates is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region V, within 30 days of the date of the letter transmitting this Notice. This reply should be clearly marked a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation if admitted, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in

9009270236 900921  
REG5 LIC30  
46-23250-01 FDC

this Notice, an order may be issued to show cause why the license should not be modified, suspended, or revoked or why such other action as may be proper should not be taken. Consideration may be given to extending the response time for good cause shown.

FOR THE NUCLEAR REGULATORY COMMISSION



Robert J. Pate, Chief  
Nuclear Materials and  
Fuel Fabrication Branch

Dated at Walnut Creek, California  
this 21<sup>st</sup> day of September 1990.