## SEP 1 8 1990

Central Wisconsin Engineers ATTN: Hooshang Zeyghami, P.E. 903 Grand Avenue Rothschild, WI 54474 License No. 48-24978-01 Docket No. 030-30040

Gentlemen:

This refers to the routine safety inspection conducted by Mr. W. P. Reichhold of this office on August 28, 1990, of activities authorized by NRC Byproduct Material License No. 48-24978-01, and to the discussion of our findings with you at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

On August 28, 1990, our inspector saw that the source rod had not been locked in the shielded position on a moisture/density gauge that was not in use. In your response to this letter, please describe your actions to make sure the source rods are locked in the shielded position when your gauges are not in use.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

00213

George M. McCann, Chief Nuclear Materials Safety Section 1

Enclosure: Notice of Violation

RIII pur holo

RIII Hamingola

Reichhold/kjc McCann

9009280170 900913 REG3 LIC30 48-24978-01 PDC TE07