

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | I | L | D | R | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

01 | L | 6 | 0 | 5 | 0 | 0 | 0 | 0 | 1 | 0 | 7 | 0 | 9 | 1 | 4 | 7 | 8 | 8 | 1 | 0 | 0 | 3 | 7 | 8 | 9

02 | During normal operation while performing DOS 1600-1, the emergency condenser outlet  
03 | valve M0101 failed to close remotely from control room. The valve would open as  
04 | required so the event was of little safety significance. Similar events reported as  
05 | Unit 1 Incident #70-6, 70-10, 70-11, 71-6, 73-17 and R.O. 50-010/1977-44.

09 | C | E | 11 | E | 12 | B | 13 | V | A | L | V | O | P | 14 | B | 15 | Z | 16  
17 | 7 | 8 | 0 | 3 | 0 | 0 | 3 | L | 0  
18 | X | 18 | X | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | N | 23 | N | 24 | N | 25 | C | 2 | 5 | 5 | 26

10 | Examination found the valve operator knuckle needing lubrication, causing valve to  
11 | stick in the open position. The valve was exercised and closed manually. This valve  
12 | inaccessible except for brief periods during plant operation. The operator will be  
13 | disassembled and lubricated during the next refuel outage.

15 | E | 28 | 0 | 5 | 2 | 29 | NA | 30 | B | 31 | Surveillance testing | 32

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36

17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39

18 | 0 | 0 | 0 | 40 | NA | 41

19 | Z | 42 | NA | 43

20 | N | 44 | 7810170216 S | 45 | NA | 46