NRC FORM 366 (7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M I B R P 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 5 57 CAT 56
CON'T REPORT L 6 0 5 10 - 10 11 5 5 7 1 10 2 10 7 8 8 1 10 2 7 8 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
[0]2 During reviews associated with the Systematic Evaluation Program, splice
materials used in control and instrumentation circuits for equipment re-
[0]4 quired to operate during a postulated LOCA were deemed to be marginal in
[0]5 moisture resistance characteristics. The plant was in shutdown condition at
[0]6 the time of this evaluation and thus no hazard to the public occurred. Re-
portable based on Technical Specification 6.9.2.a.(9).
7 8 9 SYSTEM CAUSE CAUSE COMP. VALVE
CODE CODE SUBCODE SUBC
LER RO EVENT YEAR REPORT NO. 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 31 32 32 32 32 32 32 32 32 32 32 32 32 32
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
[10] [Containment penetration area splice paterials and installation techniques
[1] [used during the addition of the back-up core spray system in 1971 did not
provide adequate moisture proofing integrity. Thus, the possibility of cir-
[1]3 cuit failure due to grounding or hot shorts existed. All circuits required
for LOCA were inspected and repairs completed on 10/31/78.
PACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIP
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35
7 8 9 10 11 44 45 80
NUMBER TYPE DESCRIPTION (39) 1 7 8 9 - 11 12 13 NA PERSONNEL INJURIES 13
NUMBER DESCRIPTION (41) 1 3 0 0 0 0 0 NA 7 8 9 11 12
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION 1 9 Z 42 NA
PUBLICITY (45)
2 0 N (44) NA 68 69 80
7811070224