

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

08 | _____

(17) **LER/RO** **REPORT** **NUMBER** **EVENT YEAR** **REPORT NO.** **CODE** **TYPE** **NO.**
 [7] [8] [—] [1] [0] [8] [0] [3] [1] [—] [0]

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER					
A	18	Z	19	Z	20	Z	21	0	0	0	0	22	Y	23	Y	24	A	25	W	1	2	0	26
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The failure of FI-1496 was due to a blown power fuse. The blown fuse was replaced.

FACILITY STATUS		% POWER		OTHER STATUS (30)		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION (32)		
1	5	E	(28)	1	0	0	NA	A	(31)	Operator Observation

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 2 33 2 34 NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES										
NUMBER		TYPE		DESCRIPTION						
1	7	0	0	0	17	Z	38	NA		

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	41 NA

1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5		6		7		8		9		10		11		12	
1		2		3		4		5															

PUBLICITY
 ISSUED DESCRIPTION (45)
 2 0 IN (44) NA

Virginia Electric and Power Company
North Anna Power Station, Unit No. 1
Docket No: 50-338
Report No. LER 78-108/03-L

Attachment: Page 1 of 1

Description Of Event

During Mode 1 operations, at 100% power, feedwater flow transmitter FI-1496 on Feedwater Loop C failed low. This being a 3 channel loop and with the other two channels being operable, the flow control function was shifted to an alternate flow meter.

Probable Consequences Of Event

Since one of three feedwater channels failed low, the failed channel was placed into the trip condition. This trip is actuated by a steam/feedwater flow mismatch (one out of two) in coincidence with low water level (one of two) in any steam generator. Since the two redundant channels were still operable, no loss of protective function was incurred, therefore the public safety was not endangered. It was necessary to shift the control function to another channel.

Cause

The flow indicator failure was due to a blown power fuse.

Immediate Corrective Action

The fuse was replaced.

Scheduled Corrective Action

No further action required.

Action Taken To Prevent Recurrence

No further action required.