

# NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

DCT 2 9 1982

MEMORANDUM FOR: Thomas T. Martin, Director, Division of Engineering and

Technical Programs, Region I

John Olshinski, Director, Division of Engineering and

Technical Programs, Region II

Charles E. Norelius, Director, Division of Engineering and

Technical Programs, Region III

Richard T. Bangart, Director, Division of Vendor and

Technical Programs, Region IV

FROM: Robert L. Baer, Chief, Engineering and Technical Support

Branch, Division of Engineering and Quality Assurance, IE

SUBJECT: TASK INTERFACE AGREEMENT FOR REVIEW OF ISI INSPECTIONS OF

THICK-WALL, LARGE DIAMETER RECIRCULATION SYSTEM PIPING IN

BWR PLANTS

Enclosed for your approval is a proposed Task Interface Agreemnet related to the review of inservice inspections of thick-wall, large diameter recirculation system piping in BWR plants. The Task Interface Agreement is being transmitted concurrently to NRR for their approval.

If you have any questions or comments regarding the Task Interface Agreement, please advise me or Alex Dromerick by November 4, 1982.

Rubert L. Baer, Chief

Engineering and Technical Support Branch

Division of Engineering and Quality

Assurance, IE

Enclosure: As stated

CONTACT: Alex Dromerick

301-49-24784

DATE:

#### TASK INTERFACE AGREEMENT

PROBLEM:	system pipi		ions of thick-wa ts that are refu			
LEAD OFFIC	CE: 87 1	E / NRR	JOINT	REGION		
NOTIFICATI	ION:					
DEFENSE	77.7					
1. IE Bull Stainle	letin 82-03	Stress Corro	sion Cracking in ystem Piping at	Thick-Wall, BWR Plants	Large Diameter,	
of 2. Eva tie 3. lss	the UT methaluate.with es and effective final required by the	the assistance tiveness of ear eport on evaluate bulletin.	Regional Officerious ISI organiof the Regional the ISI organization of ISI organistion of ISI organics 1, 2, 3, and	Offices, the tion's UT meth	performance cap ods.	
2. Eva are nes 3. Pro 4. Rev NRR: Desi	quired by the luate ISI are consistent as of the Universe recommendate Lead	ne bulletin. octivities performed with the methods. mendations regalactivities at Project Manage	evaluating ISI or or med at affected ods and procedured resumption plant sites as represented as in the control of the control	ed plant sites res used to de n of power ope required. S and coordin	to assure that monstrate the eferations.	these ffective
OFFICE COC	ORDINATORS:					
R. Wessma	n	P854				( Ext.
APPROVED:			t.			(
Miles and the Control of the Control	Bert Ban	4 10/24/8	2			Ext,
IE						Ext.
(See sec	ond page)					
REGION					2. 2.372	(27492
				NRR		
	dmin. R. D E C. M 1E H. D	niezek, IE eYoung, IE ichelson, AEOD enton, NRR	S. Hanauer, NF D. Eisenhut, N R. Vollmer, NF G. Lainas, NRF R. Tedesco, NF	RR B. Pur	ahan, NRR roject Manager ple, NRR ins, IE merick, IE	

R. Tedesco, NRR

T. Novak, NRR.

T longlite A

, IE

IE

E. Case, NRR R. Mattson, NRR NRR:

1. Review the adequacy of licensees sampling plan, bases of plan, and criteria for weld selection and acceptance.

2. Review licensee's proposed repair plans as appropriate.

 Review adequacy of UT procedures and calibration standards employed at licensee's plants and inspection results including previous inspections using validated techniques.

4. Approve licensee's request for resuming power operations.

5. Determine generic significance of degradation in recirculation piping and augmented ISI requirements as necessary.

#### APPROVED:

Thomas T. Martin, Director Region I Division of Engineering and Technical Programs

John Olshinski, Director Region II
Division of Engineering and Technical Programs

Charles E. Norelius, Director Region III Division of Engineering and Technical Programs

Richard L. Bangart Director Region IV Division of Vendor and Technical Programs 158-2753

UNITED STATES

NUCLEAR REGULATORY COMMISSION

OFFICE OF INSPECTION AND ENFORCEMENT

WASHINGTON, D.C. 20555

October 14, 1932

BULLETIN NO. 82-03: STRESS CORROSION CRACKING IN THICK-WALL;

LARGE-DIAMETER, STAINLESS STEEL, RECIRCULATION

SYSTEM PIPING AT BUR PLANTS

### dressees:

ose licensees of operating boiling water reactors (BWRs) identified in Table 1 or action. All other licensees and holders of construction peraits (CPs) or information only.

#### rpose:

where a high degree of safety significance, and to require specific actions set forth below for those licensees listed in Table 1. Specifically, this ter involves the degradation in the recirculation system piping in the actor coolant pressure boundary (RCPB) that was found at the Nine Hile Point it 1 Nuclear Generating Station. This information was described in considerable detail in Information Notice 82-39, dated September 21, 1982. Action by a affected licensees identified in Table 1 is required to (1) provide a aconable level of assurance that inspections which are currently being rformed or scheduled are sufficient to detect cracking in Bl& thick-wall circulation piping welds and (2) to assist the NRC in determining the generic opificance of the piping degradation found at Nine Mile Point.

raits for information only at this time. Licensees not listed in Table 1 11 be notified by January 15, 1983 as to the scope and extent of any required tions.

## scription of Circumstances:

oring a primary system hydrotest in March 1982 at Nine Mile Point Unit 1 (MP-1), leakage was visually detected at two of the ten furnace-sensitized, circulation system safe-ends. Further visual inspection revealed three about indications and a single k-inch-long axial indication, all of which are located in the heat-affected zone of the welds where the safe-end joined be pipe. About nine months before the leak, these safe-ends were ultrasenically (UI) inspected; at that time, the inspection did not disclose any reportable indications. Subsequent to the leak, the UI procedure was modified; UI.

82081900338

### Table 1

Plants Currently in or Scheduled to be in a Refueling Hode or Extended Outage Through January 31, 1983

PLANT(S) ERSEE (Honticello Nuclear Generating Station thern States Power Company Browns Ferry Unit 2 Nuclear Generating nessee Valley Authority Station Quan Cities Unit 1 Nuclear Generating conwealth Edison Company (Station Dresdan Unit 2 Nuclear Generating Station Millstone Unit 1 Nuclear Generating theast Utilities Station Hatch Unit 1 Nuclear Generating Station orgia Power Company Brunswick Unit 1 Nuclear Generating rolina Power & Light Company Station\* Oyster Creek Ruclear Generating Station rscy Central Power & Light Company Quane Broold Nuclear Generating Station wa Electric Light & Power Company

o be performed during the November 1982 refueling outage, not the current utage.

mination of the two affected safe-ends and one other safe-end confirmed the sence of indications of intermittent cracking around the pipe's inside mater (ID). Additional exprinations revealed cracking in heat affected mater (ID) additional exprinations revealed cracking in heat affected mater (ID). Additional exprinations revealed cracking in heat affected mater (ID). Additional exprinations were extended to other med these crack indications. The UT examinations were extended to other and these crack indications. The UT examinations were extended to other disconsiderable five loops of the recirculation system. The results of these minations disclosed ID cracking in a large number of the walds examined.

boat samples removed from the area of the through-wall cracks in one re-end were sent for evaluation -- one to General Electric Co. and the other Sattelle Laboratories. In addition, a boat sample from the crack region the elbow wald was evaluated by Sylvester Associates, consultants to the the censee. The results of these metallurgical evaluations concluded that the gradation resulted from intergranular stress corrosion cracking (IGSCC) in gradation resulted from intergranular stress corrosion cracking (IGSCC) in gradation resulted region of the weld's heat affected zones.

sed on the fact that PMP-1 has furnace-sensitized safe-ends, the licensee cided to replace all 10 recirculation system safe-ends without further vestigation beyond that described above. Based on recirculation system ndings, the licensee decided to also replace all recirculation system piping the facility was shut down for safe-end replacement.

Scotecher 16, 1982, a meeting was held between General Electric, BWR censees, and NRC staff to review past IGSCC experiences and the general censees, and NRC staff to review past IGSCC experiences and the general plications of NMP-1 IGSCC degradation in main recirculation piping walds. In plications of NMP-1 IGSCC degradation in main recirculation of the HMP-1 event he staff had the benefit of the metallurgical evaluation of the HMP-1 event and an update of the general IGSCC experiences relative to all operating BWR lants.

n September 27, 1982, a meeting was held between BWR licensees and the NRC taff to discuss the extent and results of examining walds in the recirculation ystem for all BWR licensees with plants currently in or scheduled to be in a greatly greatly

o provide a reasonable level of assurance that inspections which are currently eing performed or scheduled are sufficient to detect cracking in thick-wall, ecirculation system piping welds and to assist the NRC in further evaluating his issum, the affected licensees (identified in Table 1) are requested to ake the following ections.

actions to be Taken by Licensees of EWR Facilities Identified in Table 1:

Before resuming power operations following the current refueling or extended outage, the stepsee is to demonstrate the effectiveness of

the detection capability of the ultrasonic methodology used or planned to be used to examine useds in accirculation system piping: "This demonstration shall be made on representative service induced cracked pipe samples. After the constration of the demonstration of the demonstration shall employ those procedures and standards, the same type of equipment (same transducer size, frequencies and calibration—standards), and representative UT personnel from the inservice inspection (ISI) organization utilized or to be utilized in the examinations at the plant site.\*

- 2. Sefore resuming power operations following the current refueling or a extended outage, the licensee is to provide a listing of results of recirculation system piping inspections.
- 3. Defore resuring power operations following the current refueling or fextended outage, the licensee (if the inspections indicate the presence for cracks) is to describe the corrective actions taken and report these in accordance with the appropriate regulations.
- 4. To assist NRC's further evaluation of this issue, the following shall be submitted by December 1, 1982.
  - a. A description of the sampling plan used or to be used during this outage for UT examinations of recirculation system piping welds and the bases for the plan. The description should:
    - (1) Provide an isometric drawing of the recirculation system piping showing all the welds, and the number of welds and their location that have been examined or will be examined.
    - (2) Identify criteria for weld sample selection (e.g., stress rule index, carbon content, high stress location, and their values for each weld examined).
    - (3) Describe piping material(s), including material type, diameter, and wall thickness.
    - (4) Estimate the occupational radiation exposure incurred or expected and briefly summarize measures taken to maintain individual and collective exposures as low as reasonably achievable.

We understand that Electric Power Research Institute (EPRI) has arranged to have samples from the Wine Hile Point Unit 1 plant available for industry demonstrations of UT methodology. The samples have been taken to Battelle Memorial Institute in Columbus, Ohio for characterization and subsequent use.

- b. A summary description of the UT procedures and calibration standards used or to be employed in the examination at the licensee's plant site. This description should include the scanning sensitivity, the evaluation sensitivity and the recording criteria.
- c. A summary of the results of any previous inspection of the recirculation system piping welds which used the validated examination methodology as discussed in Action Item 1 above.
- d. An evaluation of the crack-detection capability of ultrasonic mathemodology used or planned to be used to examine recirculation system piping welds. This evaluation should result from conducting the demonstration required in Action Item 1 above, and should include a comparison of the service-induced pipe crack sample to those welds actually examined in the licensee's plant in terms of pipe wall thickness and diameter, weld geometry, and materials.

The written reports required by Items 2. 3, and 4 shall be submitted to the appropriate Regional Administrator under oath or affirmation under provisions of Section 182a, Atomic Energy Act of 1954, as amended. The original copy of the cover letters and a copy of the reports shall be transmitted to the U.S. Nuclear Regulatory Commission, Document Control Desk, Washington, D.C. 20555 for reproduction and distribution.

is request for information does not require Office of Kanagement and Budget proval since the number of plants asked to provide the information is limited nine reactor plants.

though no specific request or requirement is intended, the following information would help the NRC evaluate the cost of implementing this bulletin:

- o Staff time to perform requested demonstration
- o Staff time to prepare written responses

you have any questions regarding this matter, please contact the Regional dainistrator of the NRC Regional Office or one of the technical contacts isted below.

Richard C. DeYoung, Director

Al Milany

Office of Inspection and Enforcement

echnical Contact: William J. Collins, IE 492-7275

> Warren Hazelton, NRR 492-8075