

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 1 1 1 1 1 1 1 1 1										(1)	(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)																
0 1	F	L	S	L	S	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4	L	1	5
7 3	LICENSEE CODE	14	15	LICENSE NUMBER	25	26	LICENSE TYPE	30	37	CAT	38																
CON'T	REPORT SOURCE	L	5	0	5	0	0	0	3	3	5	7	1	2	1	5	8	2	3	1	2	2	9	8	2	9	
7 9	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84		
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)																											
0 2	During normal full power operation a routine surveillance revealed that																										
0 3	neither fire pump would start automatically upon test of any of four pressure switches in the system. Immediate investigation proved that both																										
0 4	pumps could be started manually. Troubleshooting was performed and no																										
0 5	problem was found. The surveillance was reperformed satisfactorily. The																										
0 6	health and safety of the public was not affected by this event. This is																										
0 7																											
0 8	the first event of this type involving the fire pumps.																										
7 8 9	SYSTEM CODE	A	B	11	CAUSE CODE	X	12	CAUSE SUBCODE	X	13	COMPONENT CODE	I	N	S	T	R	U	14	COMP SUBCODE	C	15	VALVE SUBCODE	Z	16	30		
7 9 10	EVENT YEAR	8	2	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32		
7 17	LER/RO REPORT NUMBER	8	2	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	
7 18	ACTION TAKEN	X	Z	18	EFFECT ON PLANT	Z	19	SHUTDOWN METHOD	Z	20	HOURS	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7 21	FUTURE ACTION	Z	Z	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	
7 24	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)																										
1 0	Troubleshooting revealed that one of four firewater header pressure switches																										
1 1	was isolated. However, this should not have affected the capability of																										
1 2	the other three pressure switches to automatically start the fire pumps.																										
1 3	No other problems could be found and upon retest the system operated																										
1 4	satisfactorily.																										
7 8 9	FACILITY STATUS	E	28	1	% POWER	0	0	29	OTHER STATUS	30	METHOD OF DISCOVERY	B	31	DISCOVERY DESCRIPTION (32)													30
7 10 11	ACTIVITY CONTENT	10	11	12	13	14	15	16	OPERATOR OBSERVATION	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47			
7 15	RELEASED OR RELEASE	Z	33	Z	34	AMOUNT OF ACTIVITY	35	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	
7 16	PERSONNEL EXPOSURES	0	0	0	37	Z	38	39	NA	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	
7 17	NUMBER	0	0	0	37	Z	38	39	NA	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	
7 18	PERSONNEL INJURIES	0	0	0	40	DESCRIPTION	41	42	NA	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	
7 19	NUMBER	0	0	0	40	DESCRIPTION	41	42	NA	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	
7 20	LOSS OF OR DAMAGE TO FACILITY	Z	42	TYPE	43	DESCRIPTION	44	45	NA	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	
7 21	PUBLICITY	SOLVED	42	DESCRIPTION	43	NA	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	
7 22	NAME OF PREPARER	D. H. West	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	
7 23	PHONE	(305) 465-3550	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	