

LICENSEE EVENT REPORT

CONTROL BLOCK: [REDACTED]

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	F I L I T I P S I 3	1 0 1 0 1 - 1 0 1 0 1 0 1 - 1 0 1 0	3	4 1 1 1 1 1 1 1	4	L	1	3
7 8	LICENSE CODE	14 15	LICENSE NUMBER	16 17	LICENSE TYPE	18	19	

CONT

0 1	REPORT SOURCE	1 0 1 5 1 0 1 0 1 0 1 2 1 5 1 0	7	1 1 0 1 2 1 5 1 7 1 8	8	1 1 1 2 1 4 1 7 1 8	9
7 8	DOCKET NUMBER	50 51	52 53	54 55	56 57	58 59	60

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 1 During power operation, the 3A and 3B Intake Cooling Water (ICW) pumps were
 0 2 running and the 3C pump was in a standby status. At about 6:05 a.m., the
 0 3 3B pump motor failed and the standby pump started automatically. At this
 0 4 point, 2 ICW pumps were operable, but T.S. 3.4.5.a.1 requires 3 operable
 0 5 pumps. However, only 1 pump is required under hypothetical accident con-
 0 6 ditions (FSAR page 9.6-5), therefore, public health and safety was not
 0 7 affected. This was the first reportable occurrence of this type.

0 9	SYSTEM CODE	W I G	11	CAUSE CODE	E	12	CAUSE SUBCODE	A	13	COMPONENT CODE	M101-T101R1X1	14	COMP. SUBCODE	Z	15	VALVE SUBCODE	Z	16
7 8	REPORT NUMBER	718	9 10	17	12	13	14	15	16	17	18	19	19	20	21	22	23	
17	EVENT YEAR	718	21 22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	
18	ACTION TAKEN	L	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	
19	FUTURE ACTION	Z	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	
20	EFFECT ON PLANT	Z	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	
21	SHUTDOWN METHOD	Z	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	
22	HOURS	1010100	21 22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	
23	ATTACHMENT SUBMITTED	N	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	
24	WPRO-4 FORM SUB	N	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	
25	PRIME COMP. SUPPLIER	A	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	
26	COMPONENT MANUFACTURER	L218101	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The 3B pump motor failed because of a short circuit in the motor windings.
 1 1 The failed motor was replaced with a spare motor. The pump was inoperable
 1 2 for about 16.5 hours. T.S. 3.4.5.b.2 permits operation with 1 ICW pump
 1 3 out-of-service for up to 24 hours.

1 4	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
7 8 9	ACTIVITY STATUS	E	10	POWER	110101	12	OTHER STATUS	NA	13	14	15	16	17	18	19	20	21
15	ACTIVITY CONTENT	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
16	RELEASED OR RELEASE	Z	17	Z	18	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z
17	AMOUNT OF ACTIVITY	NA	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32

DISCOVERY DESCRIPTION (22)

Operator Observation

1 8	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
7 8 9	PERSONNEL EXPOSURES NUMBER	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
19	TYPE	Z	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34
20	DESCRIPTION	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
21	NA	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25

LOCATION OF RELEASE (25)

NA

1 9	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
7 8 9	PERSONNEL INJURIES NUMBER	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
19	DESCRIPTION	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
20	NA	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25

1 9	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1	1
7 8 9	PUBLICITY ISSUED DESCRIPTION	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
19	DESCRIPTION	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
20	NA	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25

NRC USE ONLY

NAME OF PREPARED M. A. Schoppman

PHONE: (305) 552-3802

7812040189