

LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01
VANAS1
200-00000-00
3411111
4
5

CON'T

01
REPORT SOURCE L
605000338
7110278
8
112778
9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 On 11/2/78 at about 0500 during power escalation, above 50% power, an upper flux
03 deviation alarm was received. Subsequent calculations yielded a quadrant power tilt
04 ratio of 1.026 in the upper core. This was in excess of the 1.02 limit as per
05 T.S. 3.2.4.
06
07

09
SYSTEM CODE RC 11
CAUSE CODE X 12
CAUSE SUBCODE X 13
COMPONENT CODE ZZZZZZ 14
COMP. SUBCODE Z 15
VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 78
EVENT YEAR 78
SEQUENTIAL REPORT NO. 116
OCCURRENCE CODE 03
REPORT TYPE L
REVISION NO. 0

ACTION TAKEN X 18
FUTURE ACTION X 19
EFFECT ON PLANT B 20
SHUTDOWN METHOD Z 21
HOURS 0000 22
ATTACHMENT SUBMITTED Y 23
NPRD-4 FORM SUB. N 24
PRIME COMP. SUPPLIER N 25
COMPONENT MANUFACTURER W120 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 This quadrant power tilt is believed to be due to a nonlinear detector response at
11 lower power. Subsequent evaluation of quadrant power tilt calculations revealed that
12 the tilt ratio had returned to within the 1.02 Technical Specification limit.
13
14

15 FACILITY STATUS E 28
% POWER 050 29
OTHER STATUS N/A 30
METHOD OF DISCOVERY A 31
DISCOVERY DESCRIPTION Operator Observation 32

16 ACTIVITY CONTENT Z 33
RELEASED OF RELEASE Z 34
AMOUNT OF ACTIVITY N/A 35
LOCATION OF RELEASE N/A 36

17 PERSONNEL EXPOSURES NUMBER 000 37
TYPE Z 38
DESCRIPTION N/A 39

18 PERSONNEL INJURIES NUMBER 000 40
DESCRIPTION N/A 41

19 Z 42 N/A 43

20 PUBLICITY N 44
DESCRIPTION N/A 45

7812040215

NAME OF PREPARER W. R. Cartwright

PHONE 703-894-5151

Description of Event

On 11/2/78, at approximately 0500 during Mode 1 operation (escalating in power above 50%), an upper detector flux deviation alarm was received. Analysis of the detector currents indicated the presence of a quadrant power tilt ratio of 1.026 in the upper half of the core. This was in excess of T.S. 3.2.4 limit which restricts the quadrant power tilt ratio to ≤ 1.02 .

Probable Consequences of Occurrence

The limit of 1.02 provides DNB and linear heat generation rate protection for X-Y plane power tilts. A period of two hours of operation between 1.02 and 1.09 is allowed by Technical Specifications to allow for problem analysis and correction before a power reduction is necessary to reinstate the margin of uncertainty for FQ. Since the indicated tilt was returned to below 1.02 within one hour, no detrimental effects were felt by the core. As a result, the public health and safety was not endangered by this problem.

Cause of Occurrence

There was no indication of control rod misalignment and no immediate cause for the quadrant power tilt could be found. Non-linear detector efficiency at lower power is suspected as the cause of the upper core tilt.

Immediate Corrective Action

After the presence of the tilt was noted, the initial action of T.S. 3.2.4 was followed. Rod positions were verified. Subsequent calculations of quadrant power tilt during the power escalation indicated the tilt was less than 1.02 within the two hour limitation.

Scheduled Corrective Action

No action has been scheduled since the problem appears to have been a temporary instrumentation problem at a reduced power.

Actions Taken to Prevent Recurrence

No further action required.