1.8

LICENSEE EVENT REPORT

| | COSTHOL BLOCK |
|-------|--|
| [6]] | A L J M F 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT 68 |
| 0 1 a | PREADRY L 60 0 5 10 0 0 3 4 8 01 11 12 10 7 18 6 1 2 2 0 7 18 0 0 EVENT DATE 74 78 REPORT DATE 80 |
| 0 2 | At 1405 on 11/20/78 train A river water (RW) pump No. 9 was secured due to high |
| 0 3 | vibration. RW pump No. 10 was already out of service for maintenance. T/S 3.7.5 requires |
| 0 4 | at least two independent RW loops to be operable. RW pump No. 10 was restored to an |
| 0 5 | operable status at 1411 on 11/22/78 (train A operable). T/S 3.7.5 action statement |
| 0 6 | requirements were met. RW train B was operable. The health and safety of the general |
| | public were not affected. |
| 013 | 9 80 |
| | SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBC |
| | SEQUENTIAL REPORT TYPE 17 8 |
| 110 | The high vibration was due to pump bearing damage caused by fouling of the lube/cooling |
| | piping. Train A river water pump lube/cooling piping was flushed. A design change reques |
| ПЗ | was initiated to evaluate fouling of the lube/cooling system. |
| | |
| 14 | 80 |
| 1 5 | FACILITY IS NOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E (28) 1 0 0 (29) NA A (31) NA |
| | 9 13 12 13 44 45 46 80 ICTIVITY CONTENT ELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) |
| 7 1 8 | 9 10 11 44 45 80 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) |
| | 0 0 0 3 Z 36 NA **FERSOLUCIEL INJURIES*** **BOX 11 12 13 13 80 |
| | 0 0 0 40 NA |
| | SO STATE DESCRIPTION (43) |
| BIN | NAC USE ONLY NAC USE ONLY |
| | 781227 03 NAPER N. C. Hairston, ITI PHONE (205) 899-5136 |