

Georgia Power Company  
Post Office Box 439  
Baxley, Georgia 31513  
Telephone 912 367-7781  
912 537-9444



Georgia Power

Edwin I. Hatch Nuclear Plant

23 JAN 10 1982 P12:30


December 30, 1982  
PM-82-1348

PLANT E. I. HATCH  
Special Event Report  
Docket No. 50-366

United States Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II, Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Attention: Mr. James P. O'Reilly

Pursuant to Section 3.3.6.2.a of Hatch Unit Two Technical  
Specifications, please find attached Special Report No.  
50-366/1982-007.

  
H. C. Nix  
General Manager

HCN/SBT/abb

xc: R. J. Kelly  
G. F. Head  
J. T. Beckham, Jr.  
P. D. Rice  
K. M. Gillespie  
S. B. Tipps  
R. D. Baker  
Control Room  
Document Control

OFFICIAL COPY

IE 22

8301170465 821230  
PDR ADOCK 05000366  
S PDR

## NARRATIVE FOR SPECIAL REPORT

50-366/1982-007

On December 20, 1982, with Unit I in cold shutdown for refueling and Unit II at 2418 MWt, while performing the "PEAK SHOCK ANNUNCIATOR AND RECORDER FUNCTIONAL TEST" procedure, the Triaxial Response Spectrum Recorder was found inoperable. This event is contrary to Unit II Tech. Specs. Section 3.3.6.2.a. The balance of seismic monitoring instrumentation (identified in Unit II Tech. Specs. Table 3.3.6.2-1) remained operable. Plant operation was not affected. The health and safety of the public were not affected by this event.

The cause of this event has been attributed to component failure due to some of the component's switches being damaged. The component has been shipped to the equipment manufacturer so that the necessary repairs can be made. After repairs are made by the manufacturer, and the equipment is returned to the plant site, the component will be re-installed and returned to normal operable status.