



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555-0001

March 16, 1994

Docket Nos. 50-361
and 50-362

Mr. Harold B. Ray
Senior Vice President
Southern California Edison Co.
Irvine Operations Center
23 Parker Street
Irvine, California 92718

Mr. Edwin A. Guiles
Vice President
Engineering and Operations
San Diego Gas & Electric Co.
101 Ash Street
San Diego, California 92112

Gentlemen:

SUBJECT: GENERIC LETTER 89-10, SUPPLEMENT 5, "INACCURACY OF MOTOR-OPERATED VALVE DIAGNOSTIC EQUIPMENT" STATUS FOR SAN ONOFRE NUCLEAR GENERATING STATION, UNIT NO. 2 (TAC M87998) AND UNIT NO. 3 (TAC NO. M87999)

On June 28, 1993, the NRC staff issued Supplement 5, "Inaccuracy of Motor-Operated Valve Diagnostic Equipment," to Generic Letter (GL) 89-10, "Safety-Related Motor-Operated Valve Testing and Surveillance," requesting nuclear power plant licensees and construction permit holders (1) to re-examine their Motor-Operated Valves (MOV) programs and to identify measures taken to account for uncertainties in properly setting valve operating thrust to ensure operability, and (2) to evaluate the schedule necessary to consider the new information on MOV diagnostic equipment inaccuracy and to take appropriate action in response to that information. Within 90 days of receipt of Supplement 5 to GL 89-10, licensees were required (1) to notify the NRC staff of the diagnostic equipment used to confirm the proper size, or to establish settings, for safety-related MOVs, and (2) to report whether they had taken actions or planned to take actions (including schedule) to address the new information on the accuracy of MOV diagnostic equipment.

The staff has reviewed the responses, and has found that, for the most part, licensees and permit holders have been actively addressing the uncertainties regarding the accuracy of MOV diagnostic equipment. The increased inaccuracy of MOV diagnostic equipment can raise questions regarding (1) the adequacy of torque switch settings to provide sufficient thrust while not exceeding thrust or torque structural limits and (2) the capability of actuator motors at current settings. In their responses, licensees and permit holders indicated that many MOVs had the potential for underthrusting or overthrusting as a result of the higher than expected inaccuracy of MOV diagnostic equipment. Consequently, some licensees reported that MOVs have been retested, adjusted, or modified to resolve the concerns regarding the accuracy of MOV diagnostic equipment.

You responded to Supplement 5 by letter dated September 30, 1993, which included the following statements:

1. The ITI-MOVATS Thrust Measuring Device (TMD), Teledyne Engineering sensors, and Yoke Mounted Strain Gages from Micro-Measurement are used for MOV diagnostic testing.

9403180235 940316
PDR ADOCK 05000361
G PDR

NRC FILE CENTER COPY


DF01 10

2. When an MOV is set and tested using a MOVATS TMD, a ITI-MOVATS Engineering Report 5.2 evaluation will be performed to account for the uncertainties associated with the TMD.
3. A testing program has been established to determine the accuracy of stem and yoke-mounted strain gages.
4. Documentation and validation of the new information on MOV diagnostic equipment inaccuracies and the evaluation uncertainties will be complete by the Unit 3 Cycle 8 refueling outage.

During a future inspection, the NRC staff will discuss the resolution of the MOV diagnostic equipment accuracy issue for the San Onofre units. Particularly, the staff will discuss the findings from the licensee's evaluations of MOVs setup using the TMD and whether any operability problems were identified.

This completes all efforts on TAC Nos. M87998 AND M87999. If you have any questions regarding this issue, please call me at (301) 504-3062.

Sincerely,



Mel B. Fields, Project Manager
Project Directorate V
Division of Reactor Projects III/IV/V
Office of Nuclear Reactor Regulation

cc: See next page

Messrs. Ray and Guiles
Southern California Edison Company

cc:

T. E. Oubre, Esq.
Southern California Edison Company
Irvine Operations Center
23 Parker Street
Irvine, California 92718

Chairman, Board of Supervisors
County of San Diego
1600 Pacific Highway, Room 335
San Diego, California 92101

Alan R. Watts, Esq.
Rourke & Woodruff
701 S. Parker St. No. 7000
Orange, California 92668-4702

Mr. Sherwin Harris
Resource Project Manager
Public Utilities Department
City of Riverside
3900 Main Street
Riverside, California 92522

Mr. Charles B. Brinkman, Manager
Washington Nuclear Operations
ABB Combustion Engineering Nuclear Power
12300 Twinbrook Parkway, Suite 330
Rockville, Maryland 20852

Mr. R. W. Krieger, Vice President
Southern California Edison Company
San Onofre Nuclear Generating Station
P. O. Box 128
San Clemente, California 92674-0128

Mr. Don J. Womeldorf
Chief, Environmental Management Branch
California Department of Health Services
714 P Street, Room 616
Sacramento, California 95814

San Onofre Nuclear Generating
Station, Unit Nos. 2 and 3

Mr. Thomas E. Bostrom, Project Manager
Bechtel Power Corporation
12440 E. Imperial Highway
Norwalk, California 90650

Mr. Robert G. Lacy
Manager, Nuclear Department
San Diego Gas & Electric Company
P. O. Box 1831
San Diego, California 92111

Mr. Steve Hsu
Radiologic Health Branch
State Department of Health Services
Post Office Box 942732
Sacramento, California 94234

Resident Inspector/San Onofre NPS
c/o U.S. Nuclear Regulatory Commission
Post Office Box 4329
San Clemente, California 92674

Mayor
City of San Clemente
100 Avenida Presidio
San Clemente, California 92672

Regional Administrator, Region V
U.S. Nuclear Regulatory Commission
1450 Maria Lane, Suite 210
Walnut Creek, California 94596

March 16, 1994

2. When an MOV is set and tested using a MOVATS TMD, a ITI-MOVATS Engineering Report 5.2 evaluation will be performed to account for the uncertainties associated with the TMD.
3. A testing program has been established to determine the accuracy of stem and yoke-mounted strain gages.
4. Documentation and validation of the new information on MOV diagnostic equipment inaccuracies and the evaluation uncertainties will be complete by the Unit 3 Cycle 8 refueling outage.

During a future inspection, the NRC staff will discuss the resolution of the MOV diagnostic equipment accuracy issue for the San Onofre units. Particularly, the staff will discuss the findings from the licensee's evaluations of MOVs setup using the TMD and whether any operability problems were identified.

This completes all efforts on TAC Nos. M87998 AND M87999. If you have any questions regarding this issue, please call me at (301) 504-3062.

Sincerely,

Original signed by:

Mel B. Fields, Project Manager
Project Directorate IV and V
Division of Reactor Projects III, IV, V
Office of Nuclear Reactor Regulation

cc: See next page

DISTRIBUTION:

Docket File
NRC & Local PDRs
PDV Reading File
JRoe
EAdensam
TQuay
DFoster-Curseen
MFields
OGC
ACRS (10)
KPerkins, RV
AHansen, PD3-3
TScarborough, EMEB

| | | | |
|--------|-------------------|----------------|------------------|
| OFFICE | PDV/LA <i>JFC</i> | PDV/PM | PDV/D <i>RP</i> |
| NAME | DFoster-Curseen | MFi. <i>MS</i> | TQuay <i>for</i> |
| DATE | 3/15/94 | 3/16/94 | 3/16/94 |

OFFICIAL RECORD COPY

DOCUMENT NAME: SOGL.8910

March 16, 1994

2. When an MOV is set and tested using a MOVATS TMD, a ITI-MOVATS Engineering Report 5.2 evaluation will be performed to account for the uncertainties associated with the TMD.
3. A testing program has been established to determine the accuracy of stem and yoke-mounted strain gages.
4. Documentation and validation of the new information on MOV diagnostic equipment inaccuracies and the evaluation uncertainties will be complete by the Unit 3 Cycle 8 refueling outage.

During a future inspection, the NRC staff will discuss the resolution of the MOV diagnostic equipment accuracy issue for the San Onofre units. Particularly, the staff will discuss the findings from the licensee's evaluations of MOVs setup using the TMD and whether any operability problems were identified.

This completes all efforts on TAC Nos. M87998 AND M87999. If you have any questions regarding this issue, please call me at (301) 504-3062.

Sincerely,

Original signed by:

Mel B. Fields, Project Manager
Project Directorate IV and V
Division of Reactor Projects III, IV, V
Office of Nuclear Reactor Regulation

cc: See next page

DISTRIBUTION:

Docket File
NRC & Local PDRs
PDV Reading File
JRoe
EAdensam
TQuay
DFoster-Curseen
MFields
OGC
ACRS (10)
KPerkins, RV
AHansen, PD3-3
TScarborough, EMEB

| | | | |
|--------|-------------------|-------------------|-----------------|
| OFFICE | PDV/LA <i>JFC</i> | PDV/PM | PDV/D <i>OP</i> |
| NAME | DFoster-Curseen | MFields <i>MF</i> | TQuay <i>TQ</i> |
| DATE | 3/15/94 | 3/16/94 | 3/16/94 |

OFFICIAL RECORD COPY

DOCUMENT NAME: SOGL.8910