LICENSEE EVENT REPORT
CONTROL BLOCK:
3 1 C A S O S 12 2 0 0 - 0 0 0 0 - 0 0 0 4 1 1 1 1 1 1 0 57 CAT 58
SOURCE 60 61 DOCKET NUMBER 69 69 EVENT DATE 74 75 REPORT DATE 80
With the plant in Mode I and during surveillance testing in accordance
with SO23-3-3.37, the RCS water inventory balance indicated 1.91 gpm
unidentified leakage exceeding LCO 3.4.5.2 and invoking Action Statement
b. The leakage was identified and reduced to within limits in the allowable
time constraints, hence there was no impact on plant operation or the health and
safety of plant personnel or the public.
SYSTEM CAUSE CAUSE COMPONENT COME SUBCODE SUBCODE
CITO E BO PUMPIXIXO E G
THE PORT NUMBER SEQUENTIAL REPORT NO. 15 8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
ACTION FUTURE CFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER SUPPLIER MANUFACTURER MANUFACTURER GO 1 4 5 26
The excessive leakage was a result of CVCS charging pump P-192 which was isolated.
A second RCS water inventory balance completed at 1735 on December 2, 1982,
indicated a total 'eakage of 0.4 gpm. After replacing the plungers, and other pump
internals, the pump was-restored to operable status on December 7, 1982. This was
an isolated occurrence and no further corrective action is warranted.
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
ACTIVITY CONTENT 12 13 44 45 46 80  RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36)
) 8 9 10 11 44 45 80
NUMBER DESCRIPTION 39  PERSONNEL INJURIES 13
NA O O O O O O O O O O O O O O O O O O O
LOSS OF ON DAMAGE TO FACILITY (1)  TYPE DESCRIPTION  NA  B301170508 821220  PDR ADDCK 05000361  S PDR
PUBLICITY ISSUED DESCRIPTION (45)  NAC USE ONLY  NA
1 9 10 HBR / W/Morth 66 69 80:
NAME OF PREPARER H. B. Ray TIDE TIS/492-7700