

LICENSEE EVENT REPORT

CONTROL BLOCK. (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 V A S P S 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

0 1 REPORT SOURCE L 5 0 5 0 0 0 2 8 1 7 1 2 1 1 8 2 8 0 1 0 7 8 3 9
80 DOCKET NUMBER 56 59 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 With the unit at cold shutdown, PT 39B-2 revealed that snubbers 2-RC-HSS-162 &
0 3 163 and 2-RH-HSS-5 had low levels in their remote reservoirs. Also snubber
0 4 2-SHP-HSS-4A was discovered to have no fluid in it's reservoir. This event is
0 5 contrary to T.S.3.20 and reportable per T.S.6.6.2.b.(2). Piping thermal movement
0 6 was not hampered and no seismic events occurred during the inspection interval.
0 7 therefore, the health and safety of the public were not affected.

0 8 _____ 80

0 9 SYSTEM CODE C B 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE S U P P O R T 14 COMP SUBCODE D 15 VALVE SUBCODE Z 16
17 LER/RO REPORT NUMBER 8 2 21 22 SEQUENTIAL REPORT NO. 0 7 4 24 25 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 REVISION NO. 0 32
ACTION TAKEN X 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 37 40 ATTACHMENT SUBMITTED Y 23 NPROG FORM SUB. N 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER B 2 0 9 25

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Snubbers 2-RC-HSS-162 & 163 had a leak on their reservoir sight glass and 2-RH-HSS-
1 1 5 had a leak on a pipe fitting to the valve block. The sight glass was blanked
1 2 off and the pipe fitting retightened. Snubber 2-SHP-HSS-4A had a leak through
1 3 its tubing connection and was replaced.

1 4 _____ 80

1 5 FACILITY STATUS G 28 % POWER 0 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Periodic Test 32

1 6 ACTIVITY RELEASED Z 33 CONTENT OF RELEASE Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43

2 0 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45

8301170511 830107
PDR ADOCK 05000281
S PDR

NAME OF PREPARED J. L. Wilson

PHONE (804) 357-3184

11-11-77

ATTACHMENT 1

SURRY POWER STATION. UNIT NO. 2

DOCKET NO: 50-281

REPORT NO: 82-074/027.5

EVENT DATE: 12-11-82

TITLE OF THE EVENT: INOPERABLE SNUBBERS

1. Description of the Event

With the unit at cold shutdown, during the performance of regularly scheduled surveillance, PT-39B-2, (Visual Inspection - Inaccessible Snubbers as Found), two reactor coolant snubbers (2-RC-HSS-162 & 163) with common remote reservoirs and one RHR Snubber (2-RH-HSS-5) were discovered to have low fluid levels in their reservoirs. Also, a main steam snubber (2-SHP-HSS-4A) was discovered to have no fluid in its reservoir. This event is contrary to Technical Specification 3.20 and reportable per Technical Specification 6.6.2.b.(2).

2. Probable Consequences and Status of Redundant Equipment

Snubbers prevent unrestrained pipe motion that can occur during an earthquake or severe hydraulic transient while allowing for thermal pipe movement. The possible consequences of an inoperable snubber is an increased chance of pipe damage resulting from dynamic loads.

Remote reservoir low level does not prevent thermal pipe movement. There were no seismic events during the inspection interval, therefore, the health and safety of the public were not affected.

3. Cause

Snubbers 2-RC-HSS-162 & 163 had a leak around the sight glass of their common remote reservoir and 2-RH-HSS-5 had a leak from the fluid piping connection to its valve block. Snubber 2-SHP-HSS-4A had a leak from the tubing between its reservoir and valve block.

4. Immediate Corrective Action

The RC snubber's reservoir sight glass was removed, blanked off and sealed and the RHR snubber's leaking pipe fitting was retaped and tightened. Since air was suspected to have entered the main steam snubber's cylinder, it was removed and replaced with a snubber which had been tested satisfactorily.

5. Subsequent Corrective Action

None required.

6. Action Taken to Prevent Recurrence

The next performance of PT-39B-2 has been placed on an accelerated schedule.

7. Generic Implications

None.