LICENSEE EVENT REPORT

EIGENGEL EVENT HEI GITT
CONTROL BLOCK: [] [] [] [] [] [] [] [] [] [
0 1 M A Y K R 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 57 CAT 58 5
CON'T SOURCE L 6 0 5 0 0 0 0 2 9 7 1 2 0 9 8 2 8 0 1 0 7 8 3 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During plant heatup in mode 3, containment isolation valve AS-V-719, a mj
[6] [anual valve in the steamline to the emergency boiler feed pump, was foun]
old d to be leaking by the seat. This constitutes an inoperable containment
[0][1] isolation valve per T.S. 3.6.2. A similar occurrence was reported as LE]
[0] R 82-09. There were no adverse effects to the public health or safety asj
folia a result of this event.
1017: 1 4 200410 01 0120 0100
7 8 9 SYSTEM CAUSE CAUSE COMP. VALVE
TO BE SUBCODE
17 REPORT 8 2
ACTION SUTURE TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORMSUB SUPPLIER WANUFACTURER E 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 L 25 H 0 3 7 26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [1] The cause was attributed to poor valve seating. The valve, a 600 psi 1-]
[1] 1/2 inch Hancock gate valve, was isolated to comply with T.S. 3.6.2 act
[1] lion C. Repairs consisted of lapping the valve and replacing the bonnet
[1] [gasket. The valve was returned to service with no sign of leakage. Furt]
ther actions are not deemed necessary.
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 C 28 0 0 0 29 NA A 31 Operator Observation
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) 1 6 Z (33) Z (34) NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7 0 0 0 37 Z 38 NA
PERSONNEL INJURIES NUMBER DESCRIPTION (41) NA NA
80 B301170520 B30107 BD9 APOCK 0500000
TYPE DESCRIPTION NA S PDR
PUBLICITY ISSUED DESCRIPTION (45) NRC USE ONLY
2 0 Z 44 NA S68 69 NA S0. 5
L. D. French 84005 (413) 625-6140