# LICENSEE EVENT REPORT

	CONTROL BLOCK	TYPE ALL REQUIRED INFORMATION)
011	V A S P S 1 2 0 0 - 10 0 0 0 0 - 0 0	3 4 1 1 1 1 4 5 5
TNCS	REPORT L 6 10 15 10 10 12 18 10 7 11 2 10 19 1 50 00 00 12 18 10 7 11 2 10 19 1 10 10 10 10 10 10 10 10 10 10 10 10 1	8 2 8 0 1 1 0 7 8 3 9
	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  The unit was at full power on 12-9-82 when radiation	recorder RR-175 was observed
0 2		
0 13	to be inoperable while effluent releases were in prog	ress. This is contrary to
0 4	T.S3.11.B.4 and is reportable per T.S6.6.2.b(4).	All releases in progress were
0 [5]	terminated immediately. The associated radiation mon	itors, including the alarms
0 6	and automatic actuating functions were operable. The	refore, the health and safety
0 7	of the public were not affected.	
5 3		80
7 8	8 9 SYSTEM CAUSE CAUSE COMPONENT CODE	COMP VALVE SURCODE SUBCODE_
0 9	MICIO EO BO LINISITRO	S IS Z 16
	17 REPORT   8 2   1 2 3 27 28	29 30 31 32
	ACTION FUTURE SPECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED  B 18 Z 19 Z 20 Z 21 10 0 0 0 Y 23  33 33 34 35 35 37 40	NPRO_4   PRIME COMP.   COMPONENT   MANUFACTURER
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)	cable elipsed off the pulley.
10		
1 1	No reason for this slippage could be found. The drive cable was placed back on the	
1 2	pulley and the recorder returned to service.	
1 3	3	
1   4	4	08
7 8	FACILITY OTHER STATUS (30) DISCOVERY	DISCOVERY DESCRIPTION 32
1 5	TINIO III OLO NA LA CALLA ODES	rator's Observation
1 6	ACTIVITY CONTENT RELEASED OF RULEASE AMOUNT OF ACTIVITY 35	LOCATION OF RELEASE (36)
7 å	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)	
7 4	7 0 0 0 0 3 Z 3 N/A	80
[1]	PERSONNEL INJURIES NUMBER DESCRIPTION 41  R 10 10 10 1401 N/A	
, 1	LOSS OF OR DAMAGE TO FACILITY (42)	170526 830107 ADDCK 05000280
1 9	9 Z 42 N/A	PDR
	SSUED DESCRIPTION 45	NRC USE ONLY
20	N/A	68 59 80 \$
	J. L. Wilson	*= (804) 357-3184

ATTACHMENT 1

SURRY POWER STATION, UNIT NO. 1

DOCKET NO: 50-280 REPORT NO:

82-123/03L-0

EVENT DATE:

12-09-82

TITLE OF THE EVENT: RADIATION RECORDER FAILED

# 1. Description of the Event

The unit was at full power on 12-9-82 and 12-29-82 when radiation recorder RR-175 was observed to be inoperable with effluent releases in progress. This is contrary to T.S.-3.11.B.4 and is reportable per T.S. 6.6.2.b(4).

## 2. Probable Consequences and Status of Redundant Equipment

The radiation monitor recorder (RR-175) serves to record, for permanent record, the gross activity of liquids and gases being released. The recorder, in itself, does not mitigate the consequences of any system malfunction. The associated radiation monitors, including the alarm and automatic actuating functions, remained operable. The discharge tunnel radiation monitor and its recorder remained operable, therefore, the health and safety of the public were not affected.

### 3. Cause

The recorder became inoggrable when the printer's drive cable jumped off the pulley. The reason the cable jumped the pulley could not be determined.

#### 4. Immediate Corrective Action

The immediate corrective action was to terminate all releases that were in progress.

#### 5. Subsequent Corrective Action

The subsequent corrective action was to slip the cable back onto the pulley. The cable tension, pulley alignment, and general recorder performance was checked and found satisfactory.

## 6. Action Taken to Prevent Recurrence

These recorders are scheduled for replacement during this calendar year.

#### 7. Generic Implications

For a similar event, see Unit 1 LER-82-113/03L-0