

LICENSEE EVENT REPORT

CONTROL BLOCK: [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 I L D R S 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 [] 5

01 REPORT SOURCE L 0 5 0 0 0 2 3 7 1 2 1 5 8 2 3 1 2 2 8 8 2 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During normal operation, while performing LPCI valve operability surveillance,
03 (DOS 1500-1), Loop II flow test cutboard valve (1501-38B) failed to open. Safety
04 significance was minimal since LPCI was operable. First occurrence of this type of
05 failure.
06
07
08

09 SYSTEM CODE S F 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE V A L V O P 14 COMP. SUBCODE A 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 8 2 21 EVENT YEAR 8 2 22 SEQUENTIAL REPORT NO. 0 5 2 24 OCCURRENCE CODE 0 3 28 REPORT TYPE L 30 REVISION NO. 0 32

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

10 The cause of the failure was broken ears on the worm shaft clutch. The worm shaft
11 clutch was replaced and valve was successfully operated from the control room. No
12 further action deemed necessary.
13
14

15 FACILITY STATUS E 28 % POWER 0 5 5 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance Testing 32

16 ACTIVITY CONTENT Z 33 Z 34 N/A 35 AMOUNT OF ACTIVITY N/A 36 LOCATION OF RELEASE N/A 37

17 PERSONNEL EXPOSURES 0 0 0 37 Z 38 DESCRIPTION N/A 39

18 PERSONNEL INJURIES 0 0 0 40 DESCRIPTION N/A 41

19 LOSS OF OR DAMAGE TO FACILITY Z 42 DESCRIPTION N/A 43

20 PUBLICITY N 44 DESCRIPTION N/A 45

8301170529 821228
PDR ADOCK 05000237
S PDR