LICENSEE EVENT REPORT

	EICENSEE EVENT NEPONT
	CONTROL POOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N S G S 2 2 O O O O O O O O
0 1 7 8	SOURCE LOSCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	At 2100 hours, December 13, 1982, while performing surveillance procedure SP(0)4.6.1.3
0 3	on the 100' Elevation Containment Air Lock, it was determined that the leakage rate
0 4	exceeded the limit of 0.05 La at the design pressure of 47.0 psig, as required by
0 5	Technical Specification 3.6.1.3.b. The air lock was declared inoperable, and Action
0 6	Statement 3.6.1.3.a was entered.
0 7	
0 8	9 SYSTEM CAUSE CAUSE COMP. VALVE
0 9	SID 11 E 12 B 13 P E N E T R 14 SUBCODE SUBCOD
	LER RO EVENT YEAR REPORT NO. 17) REPORT NUMBER 2 23 24 26 27 28 29 30 31 32
	ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUBPLIER SUBPLIER MANUFACTURER E 18 F 19 Z 20 Z 21 0 0 0 0 12 23 142 142 143 142 143 142 143 143 144 147
10	The cause of the containment air lock leakage was excessive air flow past the inner doop
	seal. The air lock outer door was maintained in a closed position. The interior door
1 2	seal was repositioned in the groove and surveillance procedure SP(0)4.6.1.3 was performed
1 3	satisfactorily. At 1345 hours, December 14, 1982, the air lock was declared operable,
14	and Action Statement 3.6.1.3.a was terminated.
1 5	STATUS POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E 28 0 7 4 29 NA B 31 Surveillance Testing 9 10 CONTENT 12 13 45 46
1 6 A	LEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) NA PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
7 8	NUMBER TYPE DESCRIPTION (39) PERSONNEL INJURIES NUMBER DESCRIPTION (41) BO BO BO BO BO BO BO BO BO B
1 H	9 11 12 8301170537 830107 80
1 9	Z 42 NA
20	PUBLICITY SSUED DESCRIPTION 45 NAC USE ONLY
	F. Dickey (6899935-6000 Ext 3229)