

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | C | U | F | S | V | 1 | 2 | 0 | 0 | U | - | 0 | 0 | 0 | 0 | U | - | 0 | 0 | 3 | 4 | 1 | 1 | 2 | 0 | 4 | \_\_\_\_\_ | 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE 57 CAT 58

CON'T  
0 1 | L | 6 | 0 | 5 | 0 | U | 0 | 2 | 6 | 7 | 7 | 1 | 1 | 3 | 0 | 8 | 2 | 8 | 1 | 2 | 2 | 9 | 8 | 2 | 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34  
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On two occasions, on November 30, 1982, with the reactor at less than 1% thermal  
0 3 | power, two analytical system moisture monitors, ME-9306 and ME-9307, were taken out of  
0 4 | service, leaving only one operable monitor in service. This is reportable as a de-  
0 5 | graded mode of LCO 4.4.5 per Fort St. Vrain Technical Specification AC 7.5.2(b)2. No  
0 6 | accompanying occurrences. There was no effect on public health or safety. Related  
0 7 | occurrence is RO 79-38.  
0 8 | \_\_\_\_\_  
7 8 9

0 9 | SYSTEM CODE: C B (11) CAUSE CODE: X (12) CAUSE SUBCODE: Z (13) COMPONENT CODE: X X X X X X X (14) COMP SUBCODE: Z (15) VALVE SUBCODE: Z (16)  
17 | LER/RO REPORT NUMBER: 82 (17) EVENT YEAR: 82 (21) SEQUENTIAL REPORT NO.: 046 (24) OCCURRENCE CODE: 03 (28) REPORT TYPE: L (30) REVISION NO.: 0 (32)  
ACTION TAKEN: X (18) FUTURE ACTION: Z (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS: 0000 (22) ATTACHMENT SUBMITTED: Y (23) NPRD-4 FORM SUB.: N (24) PRIME COMP. SUPPLIER: Z (25) COMPONENT MANUFACTURER: ZY999 (26)  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | High moisture levels in the primary coolant resulted in water condensation within the  
1 1 | sample lines to the moisture monitors. This situation was suspected of causing er-  
1 2 | roneous reactor dewpoint temperature indications. In both events, the monitors were  
1 3 | taken out of service, the lines were purged with helium, and the monitors were re-  
1 4 | turned to service. No further corrective action is anticipated or required.  
7 8 9

1 5 | FACILITY STATUS: C (28) % POWER: 0011 (29) OTHER STATUS: N/A (30) METHOD OF DISCOVERY: A (31) DISCOVERY DESCRIPTION: Operator Observation (32)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 | ACTIVITY CONTENT: Z (33) Z (34) AMOUNT OF ACTIVITY: N/A (35) LOCATION OF RELEASE: N/A (36)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 | PERSONNEL EXPOSURES: NUMBER: 000 (37) TYPE: Z (38) DESCRIPTION: N/A (39)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 | PERSONNEL INJURIES: NUMBER: 000 (40) DESCRIPTION: N/A (41)  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 | LOSS OF OR DAMAGE TO FACILITY: TYPE: Z (42) DESCRIPTION: N/A (43) 8301180002 821229 PDR ADOCK 05000267 S PDR  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 | PUBLICITY: ISSUED: N (44) DESCRIPTION: N/A (45) NRC USE ONLY  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER: Carl Fuller PHONE: (303) 785-2224