LICENSEE EVENT REPORT

* CONTROL BLOCK: []]] [(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
M D C C 2 2 0 0 - 0 0 0 0 0 0 0
CON'T SOURCE LL 6 0 5 0 0 0 0 3 1 6 7 1 2 1 0 9 8 1 2 8 0 1 1 1 1 0 1 8 1 3 9
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0 12] [WITH THE RCS SYSTEM IN MODE 6, THE WEST RHR PUMP WAS IN SERVICE SUPPLYING CORE
COOLING AT 3000 GPM. A REACTOR COOLANT LOOP HIGH LEVEL ALARM WAS RECEIVED AND INVES-
TIGATION OF EQUIPMENT SHOWED THAT THE WEST RHR PUMP BREAKER HAD TRIPPED. THIS IS NON-
CONSERVATIVE WITH RESPECT TO TECHNICAL SPECIFICATION 3.9.8. THE PUBLIC HEALTH AND
SAFETY WERE NOT AFFECTED.
1 8 9 SYSTEM CAUSE 80
SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
LEARD EVENT YEAR REPORT NO. 17 REPORT NUMBER 8 2 2 23 24 26 27 28 29 30 31 31 32 COMPONENT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER SUPPLIER MANUFACTURER 18 2 2 2 3 24 26 27 28 29 30 31 31 32 COMPONENT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER 18 2 2 2 3 24 26 27 28 29 30 31 32 COMPONENT METHOD FORM SUB. SUPPLIER MANUFACTURER 18 2 2 2 3 30 31 32 32 COMPONENT MANUFACTURER 18 2 2 3 30 31 32 30 32 30 37 40 41 23 N 23 N 24 43 43 43 44 47
THE BREAKER TRIPPING COULD BE DETERMINED. THE WEST RHR PUMP WAS RESTARTED WITHIN
5 MINUTES AND CONTINUED OPERATING WITHOUT ANY FURTHER PROBLEMS. NO FURTHER ACTION
TITS IS PLANNED.
FACILITY STATUS SPOWER OTHER SUS 30 METHOD OF DISCOVERY DESCRIPTION 32
ACTIVITY CONTENT RELEASED OF RELEASE AT 20 46 LOCATION OF RELEASE 36
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
117 01 01 01 037 Z (38) NA
PERSONNEL INJURIES NUMBER DESCRIPTION 41) NA
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA S PDR 10 PDR AP CK 05000316 NA S PDR
PUBLICITY PUBLICITY ISSUED DESCRIPTION 45 NRC USE ONLY
NA NA LILILIA S
NAME OF PREPARER R. A. PALMER 80.