



**Commonwealth Edison**  
Zion Generating Station  
Shiloh Blvd. & Lake Michigan  
Zion, Illinois 60099  
Telephone 312/746-2084

January 10, 1983

Mr. James G. Keppler  
Regional Director  
Office of Inspection and Enforcement  
Region III  
U.S. Nuclear Regulatory Commission  
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station  
Docket No. 50-295/DPR-39  
Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-295/82-49 for Zion Generating Station. This report was reclassified today and required prompt notification. This occurrence was reported to Region III, Directorate of Regulatory Operations by telephone on 1/10/83 and by telegram/mailgram on 1/10/83.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.a(5) which states that failure or malfunction of one or more components which prevents or could prevent, by itself, the fulfillment of the functional requirements of system(s) used to cope with accidents analyzed in the SAR require a 14 day written report.

Very truly yours,

K. L. Graesser  
Superintendent  
Zion Station

cc: J. Waters

Enclosure: Reportable Occurrence Report No. 50-295/82-49

8301180137 830110  
PDR ADOCK 05000295  
S PDR

IE 22  
JAN 12 1983


January 10, 1983


To: K. L. Graesser


Subject: On-Site Review of reportable occurrence  
50-295/82-49.


We have reviewed the attached reportable occurrence addressing two inoperable hydrogen recombiners and recommend its submittal to the NRC. Failure mechanism of the Unit 1 hydrogen recombiner and corrective action to be taken is being tracked by AIR 83-01,

Prepared By:   
S. Petrowski

Station Review:   
Operating Engineer

  
Tech. Staff Supervisor

  
Assistant Superintendent

I concur and approve:   
K. L. Graesser  
Station Superintendent