

### Public Service Company of Colorado

16805 Road 19 1/2, Platteville, Colorado 80651-9298

December 29, 1982 Fort St. Vrain Unit No. 1 P-82560

Mr. John T. Collins, Regional Administrator Region IV Nuclear Regulatory Commission 611 Ryan Plaza Drive Suite 1000 Arlington, Texas 76011

> Reference: Facility Operating License No. DPR-34

> > Docket No. 50-267

Dear Mr. Collins:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/82-047, Final, submitted per the requirements of Technical Specification AC 7.5.2(b)1.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/82-047.

Very truly yours,


& Borst for

Don Warembourg Manager, Nuclear Production

DW/cls

Enclosure

cc: Director, MIPC



8301180320 821229 PDR ADOCK 05000267 S PDR

## REPORTABLE OCCURRENCE DISTRIBUTION

1

\$

â

ŝ

100

Number of Copies		
	1 (P Letter)	
Department of Energy		
See Presiden Onerations VIIICE		
Attn: California Patent Group		
1223 Broadway		
Oakland, California 94612		
	1 (P Letter)	
	I (i becos)	
Department of Energy		
tran Bernah		
Division of Nuclear Power Development		
Mail Station B-107		
Washington, D.C. 20545		
	1 (P Letter)	
	1 (P Letter)	
Department of Energy		
Attn: Project Manager		
P. O. Box 81608 San Diego, California 92138		
San Diego, California Plant	0	
	(1) (Original of P Letter)	
Mr. John T. Collins, Regional Administrator		
Paston IV		
Nuclear Regulatory Commission		
611 Ryan Plaza Drive		
Suite 1000		
Arlington, Texas 76011		
그 김 씨님은 그는 것이라는 것이 같은 것이 없는 것이 없는 것이 없다.	1 (P Letter)	
Mr. George Kuzmycz		
Nuclear Regulatory Commission		
7020 Norfolk Avenue		
Bethesda, Maryland 20034		
	1 (P Letter)	
Director		
office of Management Information and riogram		
Nuclear Regulatory Commission		
Washington, D.C. 20555		
	1 (P Letter)	
	1 (P Letter)	
INPO Records Center		
Suite 1500 1106 Circle 75 Parkway		
Atlanta, GA 30339		
Atlanta, GA 50557		
	1 (P Letter)	
Mr. Pichard Phelps, FSV, GA, Site Representative		
Compared AFORT C LOTD HIV		
12021 Unid County Road 19 1/4		
Platteville, Colorado 80651		
이는 이 방법에 다양한 것이 때 집안에 가장하는 것은 것이 가지 않는 것이 없다.	1 (P Letter)	
NRC Resident Site Inspector		
and meatures are and		

REPORT DATE:	December	29,	1982	
OCCURRENCE DATE:	December	1,	1982	

REPORTABLE OCCURRENCE 82-047 ISSUE 0 Page 1 of 3

FORT ST. VRAIN NUCLEAR GENERATING STATION PUBLIC SERVICE COMPANY OF COLORADO 16805 WELD COUNTY ROAD 19 1/2 PLATTEVILLE, COLORADO 80651-9298

REPORT NO. 50-267/82-047/03-L-0

Final

IDENTIFICATION OF OCCURRENCE:

While performing regularly scheduled surveillance tests on the plant protective system (PPS), a portion of the "A" logic, "loss of bearing water" circuitry associated with "C" helium circulator (C-2103) was found inoperable.

This constitutes operation in a degraded mode of LCO 4.4.1, Table 4.4-3, and is reportable per Fort St. Vrain Technical Specification AC 7.5.2(b)1.

#### EVENT DESCRIPTION:

On December 1, 1982, with the reactor operating at less than 2% thermal power, instrument personnel performed (SR 5.4.1.3.3b-M) the circulator bearing water pressure surveillance test. This surveillance is a pulse test of the PPS circuitry associated with a loss of helium circulator bearing water pressure.

Upon performing the portion of the test associated with "C" helium circulator, the logic circuitry was found operable to trip the circulator on loss of bearing water but failed to actuate the control relay which would allow accumulator water to be admitted to the circulator bearings. The amount of water available in the accumulator is sufficient to allow circulator coast down after a trip, and therefore, prevent damage to the bearings.

The redundant "B" logic circuitry was found operable in its entirety and would have performed per design.

#### CAUSE DESCRIPTION:

Component failure.

The "A" logic circuitry failed due to a faulty "ch p" (Z-32) in the CT-2A2 logic module of the PPS.

REPORTABLE OCCURRENCE 82-047 ISSUE 0 Page 2 of 3

# CORRECTIVE ACTION:

The logic module was removed and temporarily replaced with a spare while the faulty chip was replaced and the module functionally tested. The repaired module was installed, and the surveillance was successfully completed.

No further corrective action is anticipated or required.

REPORTABLE OCCURRENCE 82-047 ISSUE 0 Page 3 of 3

Prepared By:

uane I. Five Duane rye

Senior Technical Services Technician

Reviewed By:

Charles Fullis Charles Fuller

Technical Services Engineering Supervisor

Reviewed By:

Lee (m3

Edwin D. Hill Station Manager

Approved By:

X Boist for

Don Warembourg Manager, Nuclear Production