

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: C I O F S V I 1; LICENSE NUMBER: 0 0 - 0 0 U 0 0 - 0 0; LICENSE TYPE: 4 1 1 2 0; CAT 58: 4

REPORT SOURCE: L; DOCKET NUMBER: 0 5 0 0 0 2 6 7; EVENT DATE: 1 2 0 1 8 2; REPORT DATE: 1 2 2 9 8 2

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

During scheduled surveillance testing on the "loss of bearing water" PPS circuitry for "I" circulator, the "A" logic C12 module was found to be inoperable. This constitutes operation in a degraded mode of LCO 4.4.1 and is reportable per Fort St. Vrain Technical Specification AC 7.5.2(b)1. No accompanying occurrence. No effect on public health and safety. No similar reports.

SYSTEM CODE: I B; CAUSE CODE: E; CAUSE SUBCODE: G; COMPONENT CODE: X X X X X X X; COMP. SUBCODE: Z; VALVE SUBCODE: Z

LER/RO REPORT NUMBER: 8 2; EVENT YEAR: 8 2; SEQUENTIAL REPORT NO.: 0 4 1 7; OCCURRENCE CODE: 0 3; REPORT TYPE: L; REVISION NO.: 0

ACTION TAKEN: A; FUTURE ACTION: Z; EFFECT ON PLANT: Z; SHUTDOWN METHOD: Z; HOURS: 0 0 0 0; ATTACHMENT SUBMITTED: Y; NPRD-4 FORM SUB.: N; PRIME COMP. SUPPLIER: N; COMPONENT MANUFACTURER: G 0 6 3

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

The cause of this event was the failure of a chip (Z-32) in the CT-2A2 logic module of the PPS. The chip was replaced, the module was functionally tested, and the surveillance test was successfully completed. No further corrective action is anticipated or required.

FACILITY STATUS: C; % POWER: 0 0 1 1; OTHER STATUS: N/A; METHOD OF DISCOVERY: B; DISCOVERY DESCRIPTION: Surveillance Testing

ACTIVITY CONTENT RELEASED OF RELEASE: Z; AMOUNT OF ACTIVITY: N/A; LOCATION OF RELEASE: N/A

PERSONNEL EXPOSURES NUMBER: 0 0 0; TYPE: Z; DESCRIPTION: N/A

PERSONNEL INJURIES NUMBER: 0 0 0; DESCRIPTION: N/A

LOSS OF OR DAMAGE TO FACILITY TYPE: Z; DESCRIPTION: N/A

PUBLICITY ISSUED: N; DESCRIPTION: N/A

8301130329 821229 PDR ADOCK 05000267 S PDR

NAME OF PREPARER: Charles Fuchs; PHONE: (303) 785-2224