

LICENSEE EVENT REPORT

Update Report:

Previous Report Date: 4-15-82

CONTROL BLOCK: _____ ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0] [1] [N] [C] [B] [E] [P] [1] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [0] [4] [1] [1] [1] [1] [4] [5]
7 8 9 14 15 25 26 30 57 CAT 58

CON'T [0] [1]
 REPORT SOURCE [L] [6] [0] [5] [0] [0] [3] [2] [5] [0] [3] [1] [7] [8] [2] [8] [0] [1] [0] [5] [8] [3] [9]
60 61 66 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

[0] [2] During plant operation, a comparison of RTGB indications of suppression chamber water
 [0] [3] level revealed that RTGB instrument, 1-CAC-LR-2602, indicated a level of -31.2" while
 [0] [4] RTGB instrument, 1-CAC-LI-2601-3 indicated a level of -29.0". A check of the local
 [0] [5] level indicator determined the actual level to be -28.5". This event did not affect
 [0] [6] the health and safety of the public.

Technical Specifications 3.3.5.3, 6.9.1.9b

[0] [9] [I] [E] [11] [B] [12] [A] [13] [I] [N] [S] [T] [R] [U] [14] [T] [15] [Z] [16]
9 10 11 12 13 18 19 20

[17] [8] [2] [0] [3] [7] [0] [3] [L] [I]
21 22 23 24 26 27 28 29 30 31 32

[X] [18] [C] [19] [Z] [20] [Z] [21] [0] [0] [0] [0] [Y] [23] [Y] [24] [N] [25] [B] [0] [4] [C] [26]
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳

[1] [0] This event resulted from a change in trickle flow to the wet reference leg of the 2602
 [1] [1] recorder transmitter, 1-CAC-LT-2602, Model No. BQ15221. The trickle flow change
 [1] [2] caused the transmitter to sense an incorrect differential pressure. The trickle
 [1] [3] flow to the transmitter was properly established, and the transmitter was calibrated
 [1] [4] and returned to service.

FACILITY STATUS [E] [28] % POWER [0] [7] [8] [29] OTHER STATUS [30] NA METHOD OF DISCOVERY [A] [31] DISCOVERY DESCRIPTION [32] Operator Surveillance
7 8 9 10 12 13 44 45 46 80

ACTIVITY CONTENT RELEASED OF RELEASE [Z] [33] AMOUNT OF ACTIVITY [35] NA LOCATION OF RELEASE [36] NA
7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES NUMBER [0] [0] [0] [37] T'YPE [Z] [38] DESCRIPTION [39] NA
7 8 9 11 12 13 80

PERSONNEL INJURIES NUMBER [0] [0] [0] [40] DESCRIPTION [41] NA
7 8 9 11 12 80

LOSS OF OR DAMAGE TO FACILITY TYPE [Z] [42] DESCRIPTION [43] NA
7 8 9 10 80

ISSUED [N] [44] DESCRIPTION [45] PDR ADOCK 05000325 8301180334 830105
7 8 9 10 68 69 80

NRC USE ONLY

LER ATTACHMENT - RO #1-82-37

Facility: BSEP Unit No. 1

Event Date: March 17, 1982

As a result of an event involving this instrumentation on Unit No. 1, as reported in LER 1-81-07 and a post-TMI requirement, plant modification packages (1-80-79 and 1-80-016 for Unit No. 1 and 2-80-78 and 2-80-017 for Unit No. 2) have been developed. These modifications will install a condensing pot in the reference leg in order to increase the accuracy and reliability of this instrument, and remove the requirement to have flow in the reference leg to ensure that it is full.