

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | B | R | F | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 | 9 | 14 | 15 | 25 | 26 | 57 | 58 | 59

CONT
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 5 | 9 | 7 | 1 | 0 | 0 | 7 | 8 | 0 | 8 | 1 | 1 | 0 | 5 | 8 | 0 | 9
7 8 | 80 | 81 | 88 | 89 | 90 | 91 | 92 | 93 | 94 | 95 | 96 | 97 | 98 | 99

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | During normal operation, air differential temperature recorders TDR-90-103 and
0 3 | TDR-90-104, channel A elevation 620 to 737 MSL and channel B elevation 620 to 887 MSL
0 4 | failed at 1430. LCO of T.S. 3.2.I was entered. There was no effect on the health
0 5 | or safety of the public. There are no redundant systems. Previous events: None
0 6 |
0 7 |
0 8 |

0 9 | SYSTEM CODE: M B (11) CAUSE CODE: E (12) CAUSE SUBCODE: E (13) COMPONENT CODE: I N S T R U (14) COMP SUBCODE: R (15) VALVE SUBCODE: Z (16)
17 | LER NO REPORT NUMBER: 8 1 0 (21) SEQUENTIAL REPORT NO.: 0 7 6 (24) OCCURRENCE CODE: 0 3 (28) REPORT TYPE: L (30) REVISION NO: 0 (32)
ACTION TAKEN: D (18) FUTURE ACTION: Z (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS: 0 0 0 0 (22) ATTACHMENT SUBMITTED: Y (23) NPRD-4 FORM SUB: Y (24) PRIME COMP SUPPLIER: L (25) COMPONENT MANUFACTURER: H 1 6 5 (44)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | A component failure in Model 3450 digital voltmeter caused the problem. The volt-
1 1 | meter was repaired and the channels were tested and returned to service at 1810.
1 2 | This problem is considered random in nature and no recurrence control action is
1 3 | planned.
1 4 |

1 5 | FACILITY STATUS: E (28) % POWER: 0 9 8 (29) OTHER STATUS: NA (30) METHOD OF DISCOVERY: A (31) DISCOVERY DESCRIPTION: Operator observed (32)

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE: Z (33) Z (34) AMOUNT OF ACTIVITY: NA (35) LOCATION OF RELEASE: NA (36)

1 7 | PERSONNEL EXPOSURES NUMBER: 0 0 0 (37) TYPE: Z (38) DESCRIPTION: NA (39)

1 8 | PERSONNEL INJURIES NUMBER: 0 0 0 (40) DESCRIPTION: NA (41)

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE: Z (42) DESCRIPTION: NA (43)

2 0 | PUBLICATION ISSUED DESCRIPTION: N (44) 8011120 576 (45) NRC USE ONLY

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 8076 Technical Specification Involved T.S.3.2.I and E.T.S.3.3

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 10/7/80 Time of Occurrence 1430 Unit 0

Identification and Description of Occurrence:

Operator observed that air differential temperature recorders TDR-90-103 and TDR-90-104, Channel A elevation 620 to 737 MSL and Channel B elevation 620 to 887 MSL, failed at 1430 hours.

Conditions Prior to Occurrence:

Unit 1 at 98% power

Unit 2 refueling

Unit 3 at 99% power

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Instrument returned to service within the Technical Specification time limit.

Apparent Cause of Occurrence:

Component failure in a digital voltmeter.

Analysis of Occurrence:

There was no damage to plant equipment. No activity released. No personnel exposure or injury and no danger to the public health or safety.

Corrective Action:

Repaired the digital voltmeter, tested the channel and returned them to service at 1810.

Failure Data:

None

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 